

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

RECEIVED

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JAN 13 2009

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

HOBBSOCD

Release Notification and Corrective Action

OPERATOR

Initial Report

Final Report

Name of Company: Bridwell Oil Company	Contact: Steve Ginnings, President
Address: 810 8 th Street, Wichita Falls, TX 76301	Telephone No.: (940) 723-4351
Facility Name: NM State #7	Facility Type: Well and Tank Battery

Surface Owner: State Land	Mineral Owner	Lease No.
---------------------------	---------------	-----------

LOCATION OF RELEASE

API 30.025. ~~02407~~
24388

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A H	7	9S	33E					Lea

Latitude: N 33° 32' 57.6" Longitude: W 103° 36' 02.0"

NATURE OF RELEASE


Type of Release: Crude Oil	Volume of Release: Unknown	Volume Recovered: Unknown
Source of Release: Legacy Spill	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: Unknown
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Legacy spills at plugged well and out-of-service tank battery.

Describe Area Affected and Cleanup Action Taken.* Affected area is approximately 20' X 100' at well and 200' X 300' at tank battery. Cleanup is proposed by scraping soil from affected areas to achieve NMOCD recommended remediation action levels, collect confirmation soil samples and restore surface to New Mexico State Land Office requirements. Contaminated soil will be transported to an NMOCD permitted surface waste management or disposal facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Steve Ginnings	Approved by District Supervisor: 	
Title: President	Approval Date: 1.13.09	Expiration Date: 3.13.09
E-mail Address: sginnings@wf.net	Conditions of Approval:	
Date: January 9, 2009	Phone: (970) 723-4351	Attached <input type="checkbox"/> IRP# 2049

* Attach Additional Sheets If Necessary

FGRL0901453228

RECEIVED

JAN 13 2009

HOBBSOCD