

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

| | |
|---|----------------------------|
| Name of Company Apache Corporation | Contact Natalie Gladden |
| Address P.O. Box 1849 Eunice, NM 88231 | Telephone No. 575-390-4186 |
| Facility Name WBDU Cntl Bty (near WBDU #63) | Facility Type Battery |
| Surface Owner Deck | Mineral Owner State |
| Lease No. ^{FIP1} 30-025-38267 | |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| D | 16 | 21S | 37E | 110 | From north line | 1195 | From west line | Lea |

Latitude _____ Longitude _____

WTE 25'

NATURE OF RELEASE

| | | |
|--|---|----------------------|
| Type of Release Produced Water | Volume of Release 400 | Volume Recovered 380 |
| Source of Release Injection line | Date 1/2/09 | Date 1/2/09 |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Buddy Hill | |
| By Whom? Natalie Gladden | Date and Hour 1/2/09 2pm | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Injection line leak. This is a new line going to the new WBDU Central Tank Battery. There are two trenches that are dug out and uncovered, all fluid remained inside these two trenches. A vacuum truck was called out and recovered 380bbls of fluid

Describe Area Affected and Cleanup Action Taken.*

Site will be remediated to NMOCD Guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|--|--|-----------------------------------|
| Signature: <i>Natalie Gladden</i> | OIL CONSERVATION DIVISION | |
| Printed Name: Natalie Gladden | <i>J. Johnson</i> Approved by District Supervisor: ENVIRONMENTAL ENGINEER | |
| Title: EH&S Environmental Tech | Approval Date: 1.22.09 | Expiration Date: 3.22.09 |
| E-mail Address: natalie.gladden@apachecorp.com | Conditions of Approval: | Attached <input type="checkbox"/> |
| Date: 1/9/09 Phone 575-390-4186 | | IRP# 09.01.2058 |

* Attach Additional Sheets If Necessary

FGRL 0902742021