

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address P.O. Box 1849 Eunice NM 88231	Telephone No. 575-390-4186
Facility Name WBDU Central Battery	Facility Type Battery-Production
Near WBDU #63	

Surface Owner Deck	Mineral Owner State	Lease No. 30-025-38267
--------------------	---------------------	------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	16	21S	37E	110	FNL	1195	FWL	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

WTR 25'

**NATURE OF RELEASE**

Type of Release Hydrocarbons/Produced Water	Volume of Release 45	Volume Recovered 30
Source of Release Frac tanks ran over	Date 12/26/08	Date 12/26/08
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Buddy Hill	
By Whom? Natalie Gladden	Date 12/26/08 1:05pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Frac Tanks ran over leaking inside the battery which is a lined battery. All hydrocarbon material was immediately picked up and hauled to Sundance Disposal.

Describe Area Affected and Cleanup Action Taken.\*  
Follow NMOCD Guidelines for remediation

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Natalie Gladden</i>	<b>OIL CONSERVATION DIVISION</b> <i>Johnson</i>	
Printed Name. Natalie Gladden	Approved by District Supervisor <b>ENVIRONMENTAL ENGINEER</b>	
Title: EH&S Environmental Tech	Approval Date: 1.22.09	Expiration Date: 3.22.09
E-mail Address: natalie_gladden@apachecorp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1/2/09 Phone: 575-390-4186		IRP# 09.1.2056

\* Attach Additional Sheets If Necessary

FGRL0902749252