

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company	CHESAPEAKE OPERATING, INC.	Contact	BRADLEY BLEVINS
Address	P. O. BOX 190 HOBBS, NM 88241	Telephone No.	505-391-1462
Facility Name	SV Big Bertha No. 1	Facility Type	Tank Battery

Surface Owner	STATE	Mineral Owner		Lease No.	
---------------	-------	---------------	--	-----------	--

LOCATION OF RELEASE API #30-025-33883

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	11	16S	36E	2081	NORTH	1870	WEST	LEA

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	120 BBLS	Volume Recovered	110 BBLS
Source of Release	Water tank ran over after the high level alarm failed	Date and Hour of Occurrence	1/20/09 1:30 P.M.	Date and Hour of Discovery	1/20/09 3:00 P.M.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Bradley Blevins	Buddy Hill			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Date and Hour 1/23/08 1:30 PM			
If YES, Volume Impacting the Watercourse.					

WATER @ 70'

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
High level alarm failed & water tank ran over into lined containment area. Vacuum trucks were used to recover free fluid. Approximately 10 bbls of fluid escaped outside containment.

Describe Area Affected and Cleanup Action Taken *
110 BBLS of fluid was recovered. Immediate remedial operations were commenced by soil removal. Remedial actions and test results will be furnished with the final C-141.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>		OIL CONSERVATION DIVISION	
Printed Name: <i>Bradley Blevins</i>		Approved by District Supervisor: <i>Jeffrey DeRuy</i>	
Title: <i>E.H. 5</i>	Approval Date: <i>01/27/09</i>	Expiration Date: <i>03/30/09</i>	
E-mail Address: <i>bradley.blevins@CHK.COM</i>	Conditions of Approval: <i>DELIVER/REMED TO CLEAN + 1. SUBMIT FINAL C-141 BY 03/30/09</i>		Attached <input type="checkbox"/>
Date: <i>1-26-09</i>	Phone: <i>505-441-0341</i>	IRP-09-01-2065	

* Attach Additional Sheets If Necessary

FGRL0902750021