

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**RECEIVED**

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised October 10, 2003

FEB 12 2009

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**HOBBSOCD**

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company ConocoPhillips Company	Contact Jesse A. Sosa
Address 3300 N. "A" St., Bldg. 6 #247 Midland, TX 79705-5	Telephone No. (505)391-3126
Facility Name SEMU Eumont 4" Trunk Line (SEMU # 145)	Facility Type Oil Trunk Line
Surface Owner OCD	Mineral Owner BLM
Lease No. API # 30-025-34976	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	25	20S	37E	1830	North	810	West	Lea

Latitude N 32 32.755 Longitude W 103 12.643

**NATURE OF RELEASE**

Type of Release Oil	Volume of Release 23	Volume Recovered 14
Source of Release Trunkline leak	Date and Hour of Occurrence 8 AM 2/9/09	Date and Hour of Discovery 2/9/09 8 a
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD & BLM	
By Whom? Jesse Sosa	Date and Hour 2/12/09 1:40 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

WATER @ 65'



Describe Cause of Problem and Remedial Action Taken.\*

While making rounds MSO found leak on SEMU Eumont 4" steel trunk line next to SEMU Well #145. MSO shut in wells and isolated leak. He installed an emergency clamp on trunk line. A vacuum truck was called out and 14 BO was recovered.

Describe Area Affected and Cleanup Action Taken.\*

Affected area was 25 feet X 50 feet on pasture. Area will be remediated by digging out contaminated soil and talking to Landfarm. New soil will be brought in its place.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Jesse A. Sosa	Approved by District Supervisor: 	
Title: HSER Lead	Approval Date: 02/23/09	Expiration Date: 04/17/09
E-mail Address: Jesse.A.Sosa@conocophillips.com	Conditions of Approval: DELINEATE BTEX, TPH, URO/DRO & CHLORIDES TO CLEAN + 1. FINAL C-141 DUE	
Date: 02/12/2009 Phone: (505)391-3126	Attached <input type="checkbox"/> IRP-09-02-2095	

\* Attach Additional Sheets If Necessary

FGRL0905452338