

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Plains Pipeline, LP	Contact	Jason Henry
Address	2530 Hwy 214 - Denver City, Tx 79323	Telephone No.	(575) 441-1099
Facility Name	Southland Royalty 2-Inch Valve	Facility Type	Out-of-service LACT Unit Tie-in

Surface Owner	Deck Estate	Mineral Owner		Lease No.	
---------------	-------------	---------------	--	-----------	--

LOCATION OF RELEASE

NEARBY WELL 30.025.35766.00.00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	9	21S	37E					Lea

Latitude N 32.49705° Longitude W 103.16452°

NATURE OF RELEASE

Type of Release	Crude Oil	Volume of Release	5 bbls	Volume Recovered	1 bbls
Source of Release	2" valve	Date and Hour of Occurrence	01/17/2009	Date and Hour of Discovery	01/17/2009 11:45
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Larry Johnson		
By Whom?	Jason Henry	Date and Hour	01/19/2009 @ 14:25 (voice message)		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A cow rubbed against a 2" valve handle causing the valve to open at a facility where the LACT unit had been removed causing a release of crude oil. The impacted caliche and soil was excavated and stockpiled to await transportation to an approved disposal facility.

Describe Area Affected and Cleanup Action Taken.*

Released crude oil stayed on the caliche location and pooled to the south and east of the 2" valve. Impacted area will be remediated per applicable guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jason Henry	 Approved by District Supervisor: ENVIRONMENTAL ENGINEER	
Title: Remediation Coordinator	Approval Date: 1.29.09	Expiration Date: 3.29.09
E-mail Address: jhenry@paalp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 01-29-2009 Phone: (575) 441-1099		IR# 09-01-2068

* Attach Additional Sheets If Necessary

f GRL 090 5638412