

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: EnerVest Operating, LLC	Contact: William Pilkington, Brad Dean or Elroy L. Ardoin
Address: 1001 Fannin Street, Houston, Texas 77002	Telephone No. William (575)395 3367, Brad (903) 668 3817
Facility Name: Jal Field, Water Transfer Line Under Highway 18, 5.5 miles North of Jal 619222 JACK B 30 #1	Facility Type 2" Water Transfer Line with Additional Release from a 4" Transfer Line

Surface Owner RRR Cattle Company	Mineral Owner	Lease No. ^{AP1} 30-025- 0500 1128A
----------------------------------	---------------	--

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County: Lea
<u>WELL</u> N	30	24	37					

LEAK N 30 24 37 Latitude 32° 11' 16.05" Longitude 103° 11' 37.20"

NATURE OF RELEASE

Type of Release : Produced Salt Water	Volume of Release: Originally 25 BBLS. Unknown Additional.	Volume Recovered: Originally 15 BBLS., Recovering Additional Water Now
Source of Release: 2" & 4" Water Transfer Lines Under Hwy 18 North	Date and Hour of Occurrence: 5:00 PM, 2-16-09	Date and Hour of Discovery: 5:00 PM, 2-16-09
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes & <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mr. Larry Hill who was off-duty on 2-16-09 drove by and saw the site. Mr. Larry Johnson visited site on 2-18-09 and he & I communicated by phone conversation on 2-19-09 @ approximately 10:00 AM New Mexico time.	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* 2" poly water transfer line developed a leak and a digging operation commenced on 2-16-09. The 2" line was repaired with a clamp. While digging dirt for remediation the backhoe broke a 4" water transfer line in the same area releasing additional water.		
Describe Area Affected and Cleanup Action Taken.* A area approximately 100' X 100' on the west side and next to Highway 18 about 5.5 miles north of Jal, New Mexico on RRR Cattle Company property. Polluted dirt being removed and disposed of at the permitted Sundance Disposal site. After sample results and digging complete, will replace dirt with local native and natural un-contaminated dirt.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Elroy L. Ardoin	OIL CONSERVATION DIVISION	
Printed Name: Elroy L. Ardoin	<i>Elroy L. Ardoin</i> Approved by District Supervisor: ENVIRONMENTAL ENGINEER	
Title: HSE Coordinator	Approval Date: 2.19.09	Expiration Date: 4.19.09
E-mail Address: eardoin@enervest.net	Conditions of Approval:	Attached <input checked="" type="checkbox"/> RP 09-2-2090 ²⁰⁹²
Date: 2-19-09 Phone: (713) 495 6534	SUBMIT REMEDIATION PLAN	

* Attach Additional Sheets If Necessary

TO OCD FOR APPROVAL

#GRL0905760709

INCIDENT ENTERED RBIMS N LWT 0905640377