

RECEIVED

District I  
1625 N. French Dr , Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St. Francis Dr., Santa Fe, NM 87505

MAK 18 21005  
HOBBSON

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report  Final Report

Name of Company : Chevron	Contact : Ricky Heredia
Address ; P.O. Drawer 29	Telephone No.: 432-523-3655 ext 7603
Facility Name : West Dollarhide Drinkard Unit	Facility Type : 2" Lateral line to well #42

Surface Owner : Chevron	Mineral Owner	Lease No.
-------------------------	---------------	-----------

LOCATION OF RELEASE

NEARBY WELL WDDV 042 API # 36-025-12321-00-00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	32	24S	38 E					

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release : Produce Water	Volume of Release : 70 bbls	Volume Recovered : 0 bbls
Source of Release	Date and Hour of Occurrence 3/11/2009 19:30	Date and Hour of Discovery 3/11/2009 20:15
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Called OCD	
By Whom? Ricky Heredia	Date and Hour : 03/12/2009 @ 15:30	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
NA WATER @ 320'

Describe Cause of Problem and Remedial Action Taken.\*  
Internal Corrosion on 2" Steel IPC nipple from Water Injection Station failed releasing 70 bbls produce water

Describe Area Affected and Cleanup Action Taken.\*  
Free liquids were removed from the spill area The impacted area will be evaluated for depth and quantity of chlorides. If additional remediation is needed a workplan will be submitted to OCD describing the proposed actions to be taken.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Stephen Gwin</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Stephen Gwin	Approved by District Supervisor: <i>Jeffrey Selms</i>	
Title: Environmental Specialist	Approval Date: 04/02/09	Expiration Date: 06/01/09
E-mail Address: gwst@chevron.com	Conditions of Approval: SUBMIT FINAL C-141 BY	Attached <input type="checkbox"/>
Date: 03/17/2009 Phone: 432-687-7575		IRP-09-3-2142

\* Attach Additional Sheets If Necessary

FGRL 0909235759