

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr., Santa Fe, NM 87505

RECEIVED State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505
APR 15 2009
HOBSOCD

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company	Tempo Energy, Inc.	Contact	Frank Pannell
Address	PO Box 1034 Midland, TX 79702	Telephone No.	(432) 689-2951
Facility Name	State NNG #1	Facility Type	

Surface Owner	Mineral Owner	Lease No.	30-025-28245-00-00
---------------	---------------	-----------	--------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	16	26S	32E					Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produced water overflow	Volume of Release	10 bbl	Volume Recovered	
Source of Release	SWD line plugged/overflowed tank	Date and Hour of Occurrence	4/2/09	Date and Hour of Discovery	4/3/09 approx. 12:30pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully: *
WATER @ 180'

Describe Cause of Problem and Remedial Action Taken *
SWD line became plugged with salt thereby causing the SWD tank to overflow into the dyke surrounding the tank battery. Also a small spill from stuffing box occurred while well was shut-in to fix plugged line. Crew from Roadrunner environmental is removing fluids and assessing spill and remediation needed.

Describe Area Affected and Cleanup Action Taken.*
Area affected is dyke around water tank and small area around wellhead. Also small SWD spill from line break will be assessed and cleaned up

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	FRANK PANMELL	Approved by District Supervisor:	
Title:	V. P. Operations	Approval Date:	04/17/09
		Expiration Date:	06/16/09
E-mail Address:	tempoenergy@suddenlink.net	Conditions of Approval:	DELINQUENT & REMEDIATE PER NMOCD RULES
Date:	4/13/09	Phone:	(432) 689-2951
		Attached	<input type="checkbox"/>
		FINAL C-141 DUE	06/16/09
		IRP-09-4-2157	

* Attach Additional Sheets If Necessary

PGRL0910753235