

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Targa Midstream Services L P	Contact: James Lingnau 505.394.2534, Chuck Tolsma 505.631.6026
Address: PO Box 1909 Eunice, NM 88231	Telephone No. (505) 394-2534
Facility Name: Eunice Gathering System	Facility Type

Surface Owner: Range	Mineral Owner:	Lease No.
----------------------	----------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	6	22S	37E					Lea

Latitude 32.2505.718N Longitude 103.1159.256W

NATURE OF RELEASE

Type of Release: Gas and Produced Liquids	Volume of Release: 13mcf of gas and 2 to 5 barrells of liquid	Volume Recovered: None
Source of Release: ¼ hole in 20" Pipeline	Date and Hour of Occurrence: 6/12/08 2PM	Date and Hour of Discovery 6/12/08 2PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken. *

A 20 inch gathering line had a leak and released gas and any produced liquids that were lying in the line. Line was repaired with clamp and 300 feet of pipe ordered to be replaced. When pipe is replaced area will be cleaned to meet OCD guidelines.

Describe Area Affected and Cleanup Action Taken.*

Targa replaced 1000 feet of pipeline with new poly pipe. Targa excavated and sampled the area of contamination. Targa removed all contaminated soil and hauled to an approved landfarm The excavation was backfilled with 936 yards of clean soil. The area was delineated and tested per OCD Guidelines

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Don Embrey	 DISTRICT SUPERVISOR	
Title: Advisor	Approved by District Supervisor: ENVIRONMENTAL ENGINEER	Approval Date: 5.13.09 Expiration Date: ---
E-mail Address dembrey@targaresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/11/09 Phone: (432) 688-0546		IRP # 1895

* Attach Additional Sheets If Necessary

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Targa Midstream Services L P	Contact: James Lingnau 505.394.2534, Chuck Tolsma 505.631.6026
Address: PO Box 1909 Eunice, NM 88231	Telephone No. (505) 394-2534
Facility Name: Eunice Gathering System	Facility Type

Surface Owner: Range	Mineral Owner:	Lease No.
----------------------	----------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	6	22S	37E					Lea

Latitude 32.2505.718N Longitude 103.1159 256W

NATURE OF RELEASE

Type of Release: Gas and Produced Liquids	Volume of Release: 13mcf of gas and 2 to 5 barrels of liquid	Volume Recovered: None
Source of Release: 1/4 hole in 20" Pipeline	Date and Hour of Occurrence: 6/12/08 2PM	Date and Hour of Discovery 6/12/08 2PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A 20 inch gathering line had a leak and released gas and any produced liquids that were lying in the line. Line was repaired with clamp and 300 feet of pipe ordered to be replaced. When pipe is replaced area will be cleaned to meet OCD guidelines.

Describe Area Affected and Cleanup Action Taken.*
Targa will excavate and sample the area of contamination and remove any contaminated soil. The area will be cleaned and tested per OCD Guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Don Embrey</i>	OIL CONSERVATION DIVISION <i>[Signature]</i>	
Printed Name: Don Embrey	ENVIRONMENTAL ENGINEER	
Title: Advisor	Approval Date: 7.8.08	Expiration Date: 9.8.08
E-mail Address: dembrey@targaresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/22/08 Phone: (432) 688-0546	SUBMIT FINAL C 141	IRP # 1895

* Attach Additional Sheets If Necessary

Embrey, Donald M

From: Holland, Roger D.
Sent: Tuesday, May 12, 2009 7:00 AM
To: Embrey, Donald M
Subject: AMERICAN LEGION 20" PICTURES
Attachments: AMERICAN LEGION 20 INCH BACKFILL.doc

PICTURES 1&2—north site
PICTURES 3&4—south site
PICTURES 5,6,&7—middle site







05/11/2009



05/11/2009



05/11/2009