

RECEIVED

MAY 12 2009

Form C-141
Revised October 10, 2003

HOBBSOCD

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company	CHESAPEAKE OPERATING, INC.	Contact	BRADLEY BLEVINS
Address	P. O. BOX 190 HOBBS, NM 88241	Telephone No.	575-391-1462
Facility Name	Langley Greer No. 2	Facility Type	Oil Well

Surface Owner	FEDERAL	Mineral Owner		Lease No.	
---------------	---------	---------------	--	-----------	--

LOCATION OF RELEASE API #30-025-30795

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	21	22S	36E	890	NORTH	330	WEST	LEA

Latitude 32.38220 Longitude 103.27757

NATURE OF RELEASE

Type of Release	Produced water & oil	Volume of Release	50 BBLS	Volume Recovered	8 BBLS
Source of Release	Flow line ruptured	Date and Hour of Occurrence	5/4/09 10:30 A.M.	Date and Hour of Discovery	5/4/09 11:00 A.M.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Bradley Blevins	Geoff Leking			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Date and Hour 5/4/09 2:00 PM			
		If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*
WATER @ 300'

Describe Cause of Problem and Remedial Action Taken.*
A plastic flow line ruptured releasing produced water and oil. Vacuum trucks were used to recover free fluid. A backhoe was used to scrape wet soil to aid in the cleanup.

Describe Area Affected and Cleanup Action Taken.*
8 BBLS of fluid was recovered. Immediate remedial operations were commenced by soil removal. Soil removal will be done and remedial actions and test results will be furnished with the final C-141.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>	OIL CONSERVATION DIVISION	
Printed Name: BRADLEY BLEVINS	Approved by ENV ENGINEER District Supervisor: <i>Geoff Leking</i>	
Title: EHS Specialist	Approval Date: 05/12/09	Expiration Date: 07/12/09
E-mail Address: bradley.blevins@chk.com	Conditions of Approval: SAMPLE TO CLEAN	Attached <input type="checkbox"/>
Date: 5/8/09 Phone: 575-391-1462	+1. FINAL C-141 DUE BY	IBP-0905-2178

* Attach Additional Sheets If Necessary

AGRL0913239224