

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87411
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

RECEIVED
MAY 29 2009
HOBBSOCD

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Oxy USA WTP	Contact	Dusty Wilson
Address	1017 W. Stanolind Rd	Telephone No.	(575) 397-8247
Facility Name	Ramsey W.A. NCTD	Facility Type	Oil Storage

Surface Owner	Mineral Owner	Lease No.	283427
---------------	---------------	-----------	--------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	28	24s	38e					Lea

Latitude _____ Longitude _____

NATURE OF RELEASE



Type of Release	Hydrocarbon(Oil)	Volume of Release	6 bbls	Volume Recovered	4 bbls
Source of Release	Valve knocked open	Date and Hour of Occurrence	4/9/09 12:00 am	Date and Hour of Discovery	4/9/09 8:00 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Buddy Hill		
By Whom?	Dusty Wilson	Date and Hour	4/14/09 @ 2:00 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	n/a		

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
High winds caused sign at lease to fall over and hit release valve, cracking the valve open. Spill affected a 30' X 10' area on location. NMOCD(Jeff Leking) was contacted 4/30/09 at 8:50 am, and advised of soil test results taken from the spill site. Remediation efforts consisted of removal of top 3" of impacted soil, which were hauled to Sundance Services for disposal, and effected area was backfilled with clean, like , materials, as per the conversation with NMOCD Representative Leking. Copies of lab results were sent to NMOCD with the initial C-141. Remediation of this site is complete.

Describe Area Affected and Cleanup Action Taken.*
Remediated to NMOCD Requirements. Remediation complete.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Dusty L. Wilson	Approved by District Supervisor: 	
Title: HES Specialist	Approval Date: 06/01/09	Expiration Date: _____
E-mail Address: dusty_wilson@oxy.com	Conditions of Approval: _____	Attached <input type="checkbox"/>
Date: 05/20/2009	Phone: (575) 397-8210	IRP-09-5-2175

• Attach Additional Sheets If Necessary