

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	SOUTHWEST ROYALTIES, INC.	Contact	DAWN M. HOWARD
Address	6 DESTA DRIVE, STE 2100	Telephone No.	432/688-3267
Facility Name	WYATT A FEDERAL	Facility Type	BATTERY SITE
Surface Owner	BLM PRIVATE	Mineral Owner	BLM
		Lease No.	NM 94189/

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	34	17 S	33 E	1650	N	990	W	LEA

Latitude _____ Longitude _____ APL # 30.025.33600.00.00

NATURE OF RELEASE

Type of Release	OIL	Volume of Release	~100	Volume Recovered	~50
Source of Release	HOLE IN TANK	Date and Hour of Occurrence	EARLY SATURDAY, 5/23/09	Date and Hour of Discovery	NOON, SATURDAY, 5/23/09
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour 5/23/09 5:20 Paul Flowers (BLM) & Maxey Brown (NMOCD)			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

WATER @ 90'


Describe Cause of Problem and Remedial Action Taken.*

There was a hole in an oil tank at the battery and 100 BO was released but contained within the firewall.

Describe Area Affected and Cleanup Action Taken.*

A vacuum truck picked up approx. 50 BO from within the firewall. Presently raining on location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Dawn M. Howard	Approved by ENV ENGR District Supervisor: 	
Title: Operations Assistant	Approval Date: 05/28/09	Expiration Date: 07/27/09
E-mail Address: dhoward@claytonwilliams.com	Conditions of Approval: DELINEATE HORIZONTAL AND VERTICAL EXTENT OF CONTAMINATION	Attached <input type="checkbox"/> IRP-09-5-2190
Date: 5/23/09 Phone: 432/688-3267		

* Attach Additional Sheets If Necessary

IN AND OUTSIDE DIKE.
REMEDiate PER NMOCD
GUIDELINES. FINAL-C-141
DVE 07/27/09

fGRL0914855959