

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

RECEIVED
State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company ConocoPhillips Company	Contact John W. Gates
Address 3300 North A St. Bldg 6, Midland, TX 79705-5406	Telephone No. 505.391.3158
Facility Name VAC ABO Well # 10-06	Facility Type Oil and Gas

Surface Owner State Of New Mexico	Mineral Owner State Of New Mexico	Lease No 30-025-03012-00-00
--	--	------------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	34	17S	35E					Lea

Latitude **32 47. 309** Longitude **103 27.176**

NATURE OF RELEASE



Type of Release Crude Oil & Produced Water	Volume of Release 31.3bbl (3.3oil, 28water)	Volume Recovered (2oil, 21water)
Source of Release 23/8" flowline due to check valve failure	Date and Hour of Occurrence 6/22/09 1445	Date and Hour of Discovery 6/22/09 1520
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geffrey Leking by phone	
By Whom? John Gates	Date and Hour 6/24/09 0708	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

WATER@167' BGIS JARL 06/25/09

Describe Cause of Problem and Remedial Action Taken.*
23/8" flowline check valve failed resulting in 28 bbls of produced water and 3.3 bbls of crude oil being spilled onto location pad and road. MSO shut in well and generated work order to effect repairs. Vacuum truck picked up 21 bbls of water and 2 bbls of crude oil.

Describe Area Affected and Cleanup Action Taken.*
230' X 78' X 1/2" area of caliche pad and road. Spill site will be remediated in accordance with agreement with NMOCD. Vacuum truck picked up 21 bbls of water and 2 bbls of crude oil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: John W. Gates	ENVIRONMENTAL ENGINEER: Approved by District Supervisor: 	
Title: HSER Lead	Approval Date: 06/25/09	Expiration Date: 08/24/09
E-mail Address: John.W.Gates@conocophillips.com	Conditions of Approval: DELINEATE TO CLEAN +1. SUBMIT FINAL C-141 BY 08/24/09.	Attached <input type="checkbox"/>
Date: 6/25/09 Phone: 505.391.3158	IRP-09-6-2215	

• Attach Additional Sheets If Necessary

FGRH0917639553