

District I
1625 N. French Dr., Hobbs, NM 88248
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

RECEIVED
State of New Mexico
Energy Minerals and Natural Resources
JUL 24 2009
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505
HOBBSOCD

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company PRIDE ENERGY COMPANY	Contact MATTHEW L. PRIDE
Address P.O. BOX 701950, TULSA, OK 74170-1950	Telephone No. 918-524-9200
Facility Name SOUTH FOUR LAKES UNIT	Facility Type SALT WATER TANK
Surface Owner A.D. JONES ESTATE, INC.	Mineral Owner STATE OF NEW MEXICO
Lease No. E-2064; 937-2; E-596-1	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	2	12S	34E	1980	NORTH	1980	EAST	LEA

Latitude _____ Longitude _____ NEARBY WELL S, 4 LAKES UNIT 602
API # 30.025.01852.00.00

NATURE OF RELEASE

Type of Release SALT WATER	Volume of Release 490 bbls.	Volume Recovered 490 bbls.
Source of Release SALT WATER TANK/TRIPLEX PUMP	Date and Hour of Occurrence 7/16/09 Approx 1:00 a.m	Date and Hour of Discovery 7/16/09 6:00 a.m
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking (NMOCD) and Maxey Brown (NMOCD)	
By Whom? MATTHEW L. PRIDE	Date and Hour 7/16/09 Approx. 2:00 p.m. MST	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

WATER @ 26'

Describe Cause of Problem and Remedial Action Taken.*
Nipple on triplex pump broke and caused a saltwater leak; we replaced the nipple on the triplex pump.

Describe Area Affected and Cleanup Action Taken.*
All saltwater was contained inside the diked area around the tank battery. A vac. truck picked up the saltwater and properly disposed of it in an offsite commercial disposal well.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Matthew L. Pride</i>	OIL CONSERVATION DIVISION	
Printed Name: By: Pride Production Co., Inc. Title: General Partner	Approved by ENV ENGINEER! District Supervisor: <i>Geoffrey Leking</i>	
Title: By: Matthew L. Pride Title: President	Approval Date: 07/27/09	Expiration Date: 09/25/09
E-mail Address: mattp@pride-energy.com	Conditions of Approval: DELINEATE TO CLEAN + 1. REMEDIATE EXCAVATE ABLE MATERIAL AS APPROPRIATE	Attached <input type="checkbox"/>
Date: 7/22/09 Phone: 918-524-9200	IRP - 09.7.2232	

* Attach Additional Sheets If Necessary
SUBMIT FINAL C-141 BY 09/25/09
ORIGINAL COPY RECEIVED 07/24/09
PGL 0920931193
NM-C141 DOC

RECEIVED

District I
1625 N. French Dr., Hobbs, NM 88240

District II
1301 W Grand Avenue, Artesia, NM 88201

District III
1000 Rio Brazos Road, Aztec, NM 87410

District IV
1220 S St Francis Dr., Santa Fe, NM 87505

JUL 24 2009

HOBBSOCD

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company PRIDE ENERGY COMPANY	Contact MATTHEW L. PRIDE
Address P.O. BOX 701950, TULSA, OK 74170-1950	Telephone No. 918-524-9200
Facility Name SOUTH FOUR LAKES UNIT	Facility Type SALT WATER TANK

Surface Owner A.D. JONES ESTATE, INC.	Mineral Owner STATE OF NEW MEXICO	Lease No. E-2064; 937-2; E-596-1
---------------------------------------	-----------------------------------	----------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	2	12S	34E	1980	NORTH	1980	EAST	LEA

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release SALT WATER	Volume of Release 490 bbls.	Volume Recovered 490 bbls.
Source of Release SALT WATER TANK/TRIPLEX PUMP	Date and Hour of Occurrence 7/16/09 Approx. 1:00 a.m.	Date and Hour of Discovery 7/16/09 6:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking (NMOCD) and Maxey Brown (NMOCD)	
By Whom? MATTHEW L. PRIDE	Date and Hour 7/16/09 Approx. 2:00 p.m. MST	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

WATER @ 26'

Describe Cause of Problem and Remedial Action Taken.*
Nipple on triplex pump broke and caused a saltwater leak; we replaced the nipple on the triplex pump.

Describe Area Affected and Cleanup Action Taken.*
All saltwater was contained inside the diked area around the tank battery. A vac truck picked up the saltwater and properly disposed of it in an offsite commercial disposal well.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Matthew L. Pride</i>	OIL CONSERVATION DIVISION	
Printed Name: By: Pride Production Co., Inc. Title: General Partner	Approved by <u>ENV ENGINEER:</u> <u>District Supervisor:</u> <i>Geoffrey Leking</i>	
Title: By: Matthew L. Pride Title: President	Approval Date: 07/27/09	Expiration Date: 09/25/09
E-mail Address: mattp@pride-energy.com	Conditions of Approval: DELIVERATE TO CLEAN +1. REMEDIATE EXCAVATABLE MATERIAL AS APPROPRIATE. SUBMIT	Attached <input type="checkbox"/>
Date: 7/22/09 Phone: 918-524-9200	FINAL C-141 BY 09/25/09	IRP-09.7.2232

* Attach Additional Sheets If Necessary

2ND COPY OF ORIGINAL C-141 REVD 07/24/09

PRIDE ENERGY COMPANY

Physical Address: Kensington Tower
2250 East 73rd Street, Suite 550
Tulsa, Oklahoma 74136

Mailing Address: P.O. Box 701950
Tulsa, Oklahoma 74170-1950
E-mail Address: mattp@pride-energy.com

DATE: 7/22/09

OF PAGES including cover): 2

ATTN.: State of New Mexico
Oil Conservation Division

CO: 1625 N. French DR.
Hobbs, NM 88240

TELEPHONE: _____

FAX _____

FROM: Matt Pride

TELEPHONE: (918) 524-9200

FAX (918) 524-9292

RE: South 4 Lakes Unit

Lea County, New Mexico

Comments:

Attached are 2 originals of Form C-141,

Thank you,

Matthew L. Pride

VIA Certified MAIL
Return Receipt #

91 7108 2133 7831 0787 9654

RECEIVED

JUL 24 2009

HOBBS, NM

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr, Santa Fe, NM 87505

RECEIVED State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
HOBBSD 220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company PRIDE ENERGY COMPANY	Contact MATTHEW L. PRIDE
Address P.O. BOX 701950, TULSA, OK 74170-1950	Telephone No. 918-524-9200
Facility Name SOUTH FOUR LAKES UNIT	Facility Type SALT WATER TANK

Surface Owner A.D. JONES ESTATE, INC.	Mineral Owner STATE OF NEW MEXICO	Lease No. E-2064; 937-2; E-596-1
---------------------------------------	-----------------------------------	----------------------------------

LOCATION OF RELEASE

API# 30-025-01832-06-00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	2	12S	34E	1980	NORTH	1980	EAST	LEA

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release SALT WATER	Volume of Release 490 bbls.	Volume Recovered 490 bbls.
Source of Release SALT WATER TANK/TRIPLEX PUMP	Date and Hour of Occurrence 7/16/09 Approx 1:00 a.m.	Date and Hour of Discovery 7/16/09 6.00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking (NMOCD) and Maxey Brown (NMOCD)	
By Whom? MATTHEW L. PRIDE	Date and Hour 7/16/09 Approx. 2.00 p.m. MST	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

WATER @ 26'

Describe Cause of Problem and Remedial Action Taken.*

Nipple on triplex pump broke and caused a saltwater leak; we replaced the nipple on the triplex pump.

Describe Area Affected and Cleanup Action Taken.*

All saltwater was contained inside the diked area around the tank battery. A vac. truck picked up the saltwater and properly disposed of it in an offsite commercial disposal well.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Matthew L. Pride</i>	OIL CONSERVATION DIVISION	
Printed Name: By: Pride Production Co., Inc. Title: General Partner	Approved by ENV ENGINEER: District Supervisor: <i>Geoffrey Leking</i>	
Title: By: Matthew L. Pride Title: President	Approval Date: 07/27/09	Expiration Date: 09/25/09
E-mail Address: mattp@pride-energy.com	Conditions of Approval: DELINEATE TO CLEAN +1. REMEDIATE EXCAVATABLE MATERIAL AS APPROPRIATE. SUBMIT	Attached <input type="checkbox"/>
Date: 7/22/09 Phone: 918-524-9200	IRP-09-7-2232	

* Attach Additional Sheets If Necessary

FINAL C-141 BY 09/25/09

ECOPY RCUV 07/22/09