

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr, Santa Fe, NM 87505

RECEIVED
JUL 27 2009
HOBBSOCD

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company Devon Energy	Contact <input type="checkbox"/> Roger Hernandez
Address P. O. Box 250 Artesia, NM 88211	Telephone No. <input type="checkbox"/> 575-748-5238
Facility Name Kachina 8 Federal #2	Facility Type <input type="checkbox"/> Oil Well

Surface Owner FEDERAL	Mineral Owner	Lease No. <input type="checkbox"/>
-----------------------	---------------	------------------------------------

LOCATION OF RELEASE ARI # 30-025-31371-00-00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	8	18S	33E	1830	North	660	West	Lea County, NM

NATURE OF RELEASE

Type of Release 3 Bbls oil and 3 Bbls of Produced Water	Volume of Release 6 bbls total	Volume Recovered <input type="checkbox"/> 2 BO
Source of Release Hole in fire tube	Date and Hour of Occurrence 7-21-2009 8:30 am	Date and Hour of Discovery 7-21-2009 8:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM - Trish Bad Bear 9:35 am NMOCD - Jeff Leking 9:40 AM	
By Whom? <input type="checkbox"/> Roger Hernandez	Date and Hour <input type="checkbox"/> 7-21-2009 9:40 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully *
N/A
GW @ 25'

Describe Cause of Problem and Remedial Action Taken.*
Hole in fire tube - shut well in until hole is fixed.

Describe Area Affected and Cleanup Action Taken.*
4'x20' area contained inside the berm, Called vacuum truck, picked up 2 BO, raked, and fertilized inside of berm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Roger Hernandez	Approved by <input type="checkbox"/> District Supervisor	
Title: Production Foreman	Approval Date: 08/05/09	Expiration Date: 10/05/09
Date: July 22, 2009 Phone: 575-748-5238	Conditions of Approval: DELINATE TO	Attached <input type="checkbox"/> IRP-09-8-2255

* Attach Additional Sheets If Necessary

CLEAN + 1, SUBMIT FINAL C-141
BY 10/05/09.

FURL 09 217565 22