

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

AUG 10 2009

HOBBSOCD

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	COG OPERATING LLC	Contact	Kanicia Castillo
Address	550 W. Texas, Suite 1300 Midland, TX 79701	Telephone No.	432-685-4332
Facility Name	BC Federal # 1	Facility Type	Battery -100 yards south of battery

Surface Owner	Federal	Mineral Owner		Lease No	30-025-34733
---------------	---------	---------------	--	----------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	20	17S	32E	330	NORTH	1575	WEST	LEA

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produced Water & Oil	Volume of Release	40bbbls	Volume Recovered	10bbbls
Source of Release header in mainline		Date and Hour of Occurrence	7/30/09 10:00pm	Date and Hour of Discovery	7/30/09 11:00pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jeff Leking - OCD Trishia Bad Bear - BLM		
By Whom?	Kanicia Castillo	Date and Hour	07/31/09 2:35pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			



If a Watercourse was Impacted, Describe Fully.*

WATER @ 160'

Describe Cause of Problem and Remedial Action Taken *
6" SWD hole in header to mainline of the BC Federal & MC Federal leases Hole has been repaired.

Describe Area Affected and Cleanup Action Taken.*
We are lining out the battery and beginning to recover fluids. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for your approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kanicia Castillo	Approved by ENV ENGINEER: District Supervisor 	
Title: Regulatory Analyst	Approval Date: 08/17/09	Expiration Date: 10/16/09
E-mail Address: kearrillo@conchoresources.com	Conditions of Approval: SUBMIT FINAL C-141 BY 10/16/09, DELINEATE	Attached <input type="checkbox"/> IRP-09.8.2270
Date: 08/10/09 Phone: 432-685-4332		

* Attach Additional Sheets If Necessary

TO CLEAR +1.

FGRL 09 22960121