

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

AUG 10 2009

HOBBSOCD

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company COG OPERATING LLC	Contact Kanicia Carrillo
Address 550 W. Texas, Suite 100 Midland, TX 79701	Telephone No. 432-685-4332
Facility Name - West Pearl 36 State #1	Facility Type- Battery

Surface Owner State	Mineral Owner	Lease No. 30-025-38079
---------------------	---------------	------------------------

LOCATION OF RELEASE

Unit Letter F	Section 36	Township 19S	Range 34E	Feet from the 1210	North/South Line North	Feet from the 2195	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release-Produced Water	Volume of Release-30bbbs	Volume Recovered- 20bbbs
Source of Release- Water Tank	Date and Hour of Occurrence- 7/28/09- 10.00 pm	Date and Hour of Discovery 7/28/09-11:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bracher NMOCD District 2, Eddy Co Terry Gregston BLM	
By Whom? Pat Ellis	Date and Hour 6/9/09 @ 1 00pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	
If a Watercourse was Impacted, Describe Fully *		

WATER @ 90'

Describe Cause of Problem and Remedial Action Taken.*
Water Tank ran over due to too much volume entering facility Decreased volume by rerouting water to SWD.

Describe Area Affected and Cleanup Action Taken *
All water was contained inside firewall at facility. All standing fluid was removed; all contaminated soil will be removed. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for your approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name Kanicia Carrillo	Approved by District Supervisor	
Title: Regulatory Analyst	Approval Date: 08/17/09	Expiration Date: 10/16/09
E-mail Address: kcarrillo@conchoresources.com	Conditions of Approval: DELINEATE TO CLEAN UP. SUBMIT FINAL C-141 BY 10/16/09	Attached <input type="checkbox"/>
Date 08/10/09 Phone: 432-685-4332		IRP-09-8-2273

* Attach Additional Sheets If Necessary

FGRL 0922963143