

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

AUG 19 2009

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

f M L B 0923341169

Release Notification and Corrective Action

n M L B 092334462

161968

OPERATOR

Initial Report Final Report

Name of Company	Mesquite SWIS Inc	Contact	Clay Wilson
Address	P.O. Box 1479 88220	Telephone No.	575-706-1840
Facility Name	Exxon St Tank Battery	Facility Type	

Surface Owner	BLM	Mineral Owner	State	Lease No.	
---------------	-----	---------------	-------	-----------	--

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	16	21S	27E					Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produce water	Volume of Release	400 BBL	Volume Recovered	350 BBL
Source of Release	Flow came apart	Date and Hour of Occurrence		Date and Hour of Discovery	same
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	8-14-09 5:00 pm OCD Artesia		
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Flow line came apart due to Excel working on power lines. Have built a berm over Flow line for trucks to drive over.

Describe Area Affected and Cleanup Action Taken.* Desert Sandy vacuumed up all the water we could, will meet with Arch Company 8-19-09 Get approved and start digging out contaminated soil, haul to CRT and replace with good soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Clay Wilson</i>	OIL CONSERVATION DIVISION	
Printed Name:	CLAY L WILSON	Approved By:	<i>Mike Brumby</i> District Supervisor
Title:	Pres.	Approval Date:	AUG 21 2009
E-mail Address:	CLAY.L.WILSON@PCCN.MN.COM	Expiration Date:	
Date:	8/19/09	Conditions of Approval:	attached <input checked="" type="checkbox"/>
Phone:	575-706-1840		

* Attach Additional Sheets If Necessary

REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION

PROPOSAL BY: SEPTEMBER 21, 2009

2RP-329

i M L B 0923342158

Bratcher, Mike, EMNRD

From: Bratcher, Mike, EMNRD
Sent: Friday, August 21, 2009 2:41 PM
To: 'claywilson@pccnm.com'
Subject: Mesquite Exxon State SWD Battery Release
Attachments: Mesquite SWD Exxon Btry 8.21.09.doc

Mr. Wilson,

Please see the attached request for a corrective action work plan for the recent release of produced fluids that occurred at your Exxon State SWD Commercial Disposal Facility.

If you have any questions or concerns, please contact me.

Sincerely,

Mike Bratcher
NMOCD District 2
575-748-1283 Ext.108



New Mexico Energy, Minerals and Natural Resources Department

Bill Richardson
Governor

Joanna Prukop
Cabinet Secretary

Mark Fesmire
Division Director
Oil Conservation Division



Mesquite SWD Inc.
PO Box 1479
Carlsbad, NM 88220
ATTN: Clay Wilson

August 21, 2009

Reference: Mesquite Services Exxon State SWD Battery 16-21s-27e Eddy County, New Mexico

Mr. Wilson,

The New Mexico Oil Conservation Division District 2 Office (OCD) is in receipt of an initial report Form C-141 reporting a release of produced fluids at or near the above referenced facility site. The release reportedly occurred on or about August 14, 2009. Please submit a corrective action work plan proposal (plan) for remediation and/or removal of contaminants that may be present at this site. The plan is to be formulated based on vertical and horizontal delineation of contamination, site ranking, and OCD rules, regulations and guidelines.

A publication is available to you on the OCD website to aid in formulation of this plan. The publication may be found as follows:

<http://www.emnrd.state.nm.us/ocd>

Click on each of the following items as they appear:

- Publications
- Environmental Handbook
- Miscellaneous Guidelines
- Remediation of Leaks, Spills and Releases

Please submit this plan to the OCD District 2 Office not later than September 21, 2009. Please include any remedial or clean up actions that may have been already performed, such as any immediate response corrective actions.

Clean up/remediation requirements may be subject to other federal, state, local laws and/or regulations.

Sincerely,



Mike Bratcher
NMOCD District 2
1301 W. Grand Ave.
Artesia, NM 88210
575-748-1283 Ext.108

mike.bratcher@state.nm.us

OCD Facility Number: fMLB0923341169

Tracking: **2RP-329**

Distribution: via email: claywilson@pccnm.com
USPS Certified to the listed address

