

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88203
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

RECEIVED
AUG 10 2009
HOBBSOCD

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Devon Energy	Contact <input type="checkbox"/> Roger Hernandez
Address P. O. Box 250 Artesia, NM 88211	Telephone No. <input type="checkbox"/> 575-748-5238
Facility Name Outland State Unit #3	Facility Type <input type="checkbox"/> Gas Well

Surface Owner STATE	Mineral Owner	Lease No. <input type="checkbox"/>
---------------------	---------------	------------------------------------

LOCATION OF RELEASE

API # 3 ~ 025-35243-00-00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	11	21S	34E	660	South	990	East	Lea County

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 53 BPW	Volume Recovered <input type="checkbox"/> 0
Source of Release Fiberglass Water Tank	Date and Hour of Occurrence Sometime during nite of 8-3-09	Date and Hour of Discovery <input type="checkbox"/> August 4, 2009 9:34 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Lea County OCD (Robert Harrison)	
By Whom? <input type="checkbox"/> Ernie Duran	Date and Hour <input type="checkbox"/> 8-4-2009 1:25 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

GW @ 105



Describe Cause of Problem and Remedial Action Taken.*

Lightening from the previous night had struck the fiberglass water tank releasing 53 bbls., of produced water. The water was contained in the dike around the battery, the area is a dirt dike and none of it was recovered This is a shut-in well that is flowed once a month.

Describe Area Affected and Cleanup Action Taken *

Water was contained in the dirt dike, the area is approximately 30'x50'.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature 	OIL CONSERVATION DIVISION	
Printed Name. Ernie Duran for Roger Hernandez	Approved by <input type="checkbox"/> District Supervisor 	
Title. Asst Production Foreman	Approval Date: 08/18/09	Expiration Date: 10/18/09
Date August 6, 2009 Phone: 575-513-1768	Conditions of Approval: DELINEATE TO	Attached <input type="checkbox"/> IRP-09-8-2278

* Attach Additional Sheets If Necessary.

CLEAN +1, SUBMIT FINAL C-141
BY 11/18/09

FILE 09 26159639