

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
320 South St. Francis Dr.
Santa Fe, NM 87505
AUG 17 2008
HOBBS CO

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company ConocoPhillips Company	Contact John W. Gates
Address 3300 North A St. Bldg 6, Midland, TX 79705-5406	Telephone No. 505.391.3158
Facility Name EVGSAU Well # 3467-121	Facility Type Oil and Gas

Surface Owner State Of New Mexico	Mineral Owner State Of New Mexico	Lease No 30-025-23844-00-00
--	--	------------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	34	17S	35E					Lea

Latitude **N 32 degrees 47.467** Longitude **W. 103degrees 27.222**

NATURE OF RELEASE


Type of Release Crude Oil And Produced Water	Volume of Release 36bbl (18bbloil, 18bblwater)	Volume Recovered (14bbloil, 14bblwater)
Source of Release Flowline	Date and Hour of Occurrence 10-16-08 11:55am	Date and Hour of Discovery 10-17-08 11:55am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mark Whitaker	
By Whom? Bradley Boroughs	Date and Hour 10-17-08 6:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
WATER @ 130'

Describe Cause of Problem and Remedial Action Taken.*
The cause of the spill was due to a flowline leak due to internal / external corosion. The failed section of flowline will be replaced

Describe Area Affected and Cleanup Action Taken.*
60' X 36' and 30' X 36' area of dry pasture land with no cows present. The spill site will be delineated and remediated in accordance with NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: John W. Gates	Approved by: ENV ENGINEER: District Supervisor: 	
Title: HSER Lead	Approval Date: 08/17/09	Expiration Date: 10/16/09
E-mail Address: John.W.Gates@conocophillips.com	Conditions of Approval: SUBMIT FINAL C-141 BY 10/16/09	Attached <input type="checkbox"/>
Date:	Phone: 505.391.3158	IRP-q. 8-2264

• Attach Additional Sheets If Necessary

FGRL 0927135569