

District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

JUN - 3 2009

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-26743

**Release Notification and Corrective Action**

nMB 0927357241

**OPERATOR**

Initial Report  Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Kancia Carrillo
Address	550 W. Texas, Suite 1300 Midland, TX 79701	Telephone No.	432-685-4332
Facility Name -	GJ West Coop Unit #79	Facility Type-	North Battery

Surface Owner	Mineral Owner	Lease No.	30-015-26743
---------------	---------------	-----------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	21	17S	29E	2310	North	1460	East	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release-OIL	Volume of Release-15bbls	Volume Recovered- 12bbls
Source of Release-LACT UNIT BACK PRESSURE VALVE	Date and Hour of Occurrence- 5/28/09- 12:00 pm	Date and Hour of Discovery 5/28/09-12:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher NMOCD District 2	
By Whom? Kent Greenway	Date and Hour 5/29/09- 9:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

1/4 inch line on lact unit back pressure valve broke. Replaced back pressure valve and put lact back in service.

Describe Area Affected and Cleanup Action Taken.\*

Approximately 10' X 25' area was sprayed and affected. All spray was contained on the location pad. 12bbls oil liquid was recovered. The affected area is being dug out to a 1' depth and removed. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for your approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Kancia Carrillo	Approved by 	
Title: Regulatory Analyst	Approval Date: <b>SEP 30 2009</b>	Expiration Date: <i>N/A</i>
E-mail Address: kcarrillo@conchoresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/01/09 Phone: 432-685-4332	<i>REMEDIATION Completed</i>	

\* Attach Additional Sheets If Necessary

nMB 0927357518

2RP-346