

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

**RECEIVED**

Form C-141  
Revised March 17, 1999

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

SEP 02 2009  
HOBSOCD

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Devon Energy	Contact <input type="checkbox"/> Roger Hernandez
Address P. O. Box 250 Artesia, NM 88211	Telephone No. <input type="checkbox"/> 575-748-5238
Facility Name Mesa Verde 6 Fed #5	Facility Type <input type="checkbox"/> Oil Well

Surface Owner FEDERAL	Mineral Owner	Lease No. <input type="checkbox"/>
-----------------------	---------------	------------------------------------

**LOCATION OF RELEASE**

API # 30-025-32504-00-00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	6	024S	032E	1980	North	1980	East	Lea County, NM

**NATURE OF RELEASE**

Type of Release Oil and Produced Water	Volume of Release 5 bbls	Volume Recovered <input type="checkbox"/> 0
Source of Release Flowline	Date and Hour of Occurrence 8-27-2009 2:30 PM	Date and Hour of Discovery <input type="checkbox"/> 8-27-2009 2:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM - Lea County, NM Trish BadBear	
By Whom? <input type="checkbox"/> Roger Hernandez	Date and Hour <input type="checkbox"/> 8-28-2009 7:30 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

N/A

WATER @ 335

Describe Cause of Problem and Remedial Action Taken.\*



Leak in buried flowline, shut well in while making repairs. Replaced with poly line.

Describe Area Affected and Cleanup Action Taken.\*

8' radius around wellhead, and an area 1'x100', back dragged the location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature: 	Approved by <input type="checkbox"/> ENV. ENGINEER: <input type="checkbox"/> District Supervisor: 	
Printed Name: Roger Hernandez	Approval Date: 09/03/09	Expiration Date: 11/03/09
Title: Production Foreman	Conditions of Approval: SAMPLING CONFIRM- Attached <input type="checkbox"/> HP-09-9-2288	

\* Attach Additional Sheets If Necessary

NO CLEAN CONCENTRATIONS  
HAVE BEEN REACHED. IT BE  
PERFORMED AND ANALYSIS  
RESULTS SUBMITTED TO  
NMOCD.

FILE 09-27341991