

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

RECEIVED

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

SEP 15 2009
HOBBSOCD

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company ConocoPhillips Company	Contact John W. Gates
Address 3300 North A St. Bldg 6, Midland, TX 79705-5406	Telephone No. 505.391.3158
Facility Name EVGSAU Satellite # 1 closest well EVGSAU 1910-001	Facility Type Oil and Gas

Surface Owner State Of New Mexico	Mineral Owner State Of New Mexico	Lease No 30-025-02824-00-00
--	--	------------------------------------

LOCATION OF RELEASE

Unit Letter J	Section 19	Township 17S	Range 35E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	----------------------

Latitude Longitude

NATURE OF RELEASE



Type of Release Crude Oil & Produced Water	Volume of Release 10.6bbl (3oil, 7.6water)	Volume Recovered (3oil, 7water)
Source of Release The release originated from a hole in a 4" elbow on a steel bypass line due to internal/external corrosion.	Date and Hour of Occurrence 09/8/09 1715	Date and Hour of Discovery 09/8/09 1730
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
WATER @ 73'

Describe Cause of Problem and Remedial Action Taken.*
The release originated from a hole in a 4" elbow on a steel bypass line due to internal/external corrosion. A PAC Employee discovered the release and immediately closed the dump valve located behind the bypass line which effectively stopped the release. He then notified the COPC Lease Operator who in turn notified supervision. A vacuum truck was called and recovered 3bbls of crude oil and 7 bbls of produced water.

Describe Area Affected and Cleanup Action Taken.*
The affected area is a 40' X 30' X .5" area of dry hard caliche pad with no livestock present. The spill site will be remediated in accordance with an agreement with NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: John W. Gates	Approved by ENV ENGINEER District Supervisor 	
Title: HSER Lead	Approval Date: 09/16/09	Expiration Date: 11/16/09
E-mail Address: John.W.Gates@conocophillips.com	Conditions of Approval: DELIVERATE TO CLEAN + 1. SUBMIT FINAL C-141 BY 11/16/09	Attached <input type="checkbox"/>

AGRL 0928154673

IRP-09.10.2295