

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

RECEIVED

SEP 23 2009

HOBBSOCD

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company ConocoPhillips Company	Contact John W. Gates
Address 3300 North A St. Bldg 6, Midland, TX 79705-5406	Telephone No. 505.391.3158
Facility Name MCA 2A Header	Facility Type Oil and Gas

Surface Owner Federal	Mineral Owner Federal	Lease No LC-060199A
------------------------------	------------------------------	----------------------------

LOCATION OF RELEASE

NEARBY WELL MCA UNIT 308
API # 30.025.24076.00.00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	29	17S	32E					Lea

Latitude **32.48.340** Longitude **103 47.301**

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 878.4bbl (0oil, 878.4water)	Volume Recovered (0oil, 845water)
Source of Release 2" Fiberglass Trunkline	Date and Hour of Occurrence 9/19/09 Unknown	Date and Hour of Discovery 9/19/09 0717
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Hutchins	
By Whom? Tommy Brooks	Date and Hour 9/19/09 1615	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

WATER @ 170"



Describe Cause of Problem and Remedial Action Taken.*

Leak originated from a hole in a 2" fiberglass trunkline due to fatigue. Trunkline was isolated and the 2A header

Describe Area Affected and Cleanup Action Taken.*

300' X 60' X 2" area of sandy pasture land with no livestock present. Spill site will be delineated & remediated in accordance with an agreement with NMOCD and BLM guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: John W. Gates	Approved by ENV ENGINEER District Supervisor: 	
Title: HSER Lead	Approval Date: 09/24/09	Expiration Date: 11/24/09
E-mail Address: John.W.Gates@conocophillips.com	Conditions of Approval: DELINEATE TO CLEAN UP, SUBMIT FINAL BY 11/24/09.	Attached <input type="checkbox"/>
Date: 9/21/09 Phone: 505.391.3158		IRP-09.10.2300

- Attach Additional Sheets If Necessary

FGRL0928731707