

RECEIVED

SEP 16 2009

HOBBSOCD

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2008
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Southern Union Gas Services	Contact: Rose Slade
Address: 1507 W. 15 th Monahans, Texas 79756	Telephone No.: 432-943-1100 ext. 1116
Facility Name: Monahans Field Office	Facility Type: Natural Gas Gathering
Surface Owner: D. K. Boyd	Mineral Owner
Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	21	26	37					Lea

Latitude_N32°01.485 Longitude:103°10.294

NATURE OF RELEASE

Type of Release: Crude oil, Produced water, and Natural Gas	Volume of Release: 75 barrels	Volume Recovered: 20 barrels
Source of Release: Pipeline	Date and Hour of Occurrence: not known	Date and Hour of Discovery: 9/4/09 at 8:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeffery Lecking at the NMOCD office Hobbs, NM	
By Whom? Rose Slade	Date and Hour: 9/4/09 at 9:15 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The 16" natural gas gathering line operating at approximately 37 p.s.i. developed a leak. Repair crews arrived at the leak site with a vacuum truck and started recovering the fluid of mostly water and crude oil. The leak area was excavated and the 16" natural gas line was replaced with 120 feet of pipe. The landowner was immediately notified.

Describe Area Affected and Cleanup Action Taken.*

Approximately 10,500 sq.ft. of pasture land was affected by the leak. Final remediation will follow the NMOCD recommended guidelines for leaks and spills and the landowners specifications to not remediate the contaminated soil on site and to haul the contaminated soil to the SUG landfarm according to the permit requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: *Rose L. Slade*

Printed Name: Rose L. Slade

Title: EHS Compliance Specialist

E-mail Address: rose.slade@sug.com

Date: 9/14/09 Phone: 432-940-5147

ENV. ENGINEER:
Approved by District Supervisor: *Jeffery Lecking*

Approval Date: 09/19/09 Expiration Date: 11/19/09

Conditions of Approval: DELINQUENT & SAMPLE #1, SUBMIT FINAL CEM BY 11/19/09

Attached

IRP-09.10.2309

* Attach Additional Sheets If Necessary

66760929653764