

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED
OCT 13 2009
HOBBSOCD

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: BJ Services Company	Contact: Josh Morrisette
Address: 2708 West County Road, Hobbs, NM 88240	Telephone No. 281-357-2573
Facility Name: BJ Services Yard	Facility Type: Oil Field Services Yard

Surface Owner: BJ Services Company	Mineral Owner	Lease No.
---	---------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	20	18S	38E	660	North	660	East	Lea

Latitude 32° 44' 0.11" Longitude 103° 10' 9.97"

NATURE OF RELEASE

Type of Release: Waste Water	Volume of Release: Unknown	Volume Recovered: 0
Source of Release: Leak from wastewater sump	Date and Hour of Occurrence	Date and Hour of Discovery 10/07/09 at 2:15 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Maxey Brown	
By Whom?	Date and Hour: 10/07/09 at 3:50 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



gw@60'

Describe Cause of Problem and Remedial Action Taken.*

Sump failed integrity test and cause is unknown at this time. Work plan being prepared to determine cause of leak.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Josh Morrisette	ENV ENGINEER Approved by District Supervisor: 	
Title: HSE Specialist	Approval Date: 10/14/09	Expiration Date: 12/14/09
E-mail Address: Joshua.morrisette@bjservices.com	Conditions of Approval: DELIVER TO CLEAN + V. SUBMIT FINAL C-141 BY Attached <input type="checkbox"/>	
Date: 10/9/2009 Phone: 281-357-2573	IRP-09-11-2326	

* Attach Additional Sheets If Necessary

F GR L 0930854801



October 9, 2009

UPS OVERNIGHT

New Mexico Oil Conservation Division
District I - Hobbs
Attn: Mr. Maxey Brown
1625 N. French Dr.
Hobbs, NM 88240

RECEIVED
OCT 13 2009
HOBBSOCD

RE: Release Notification – Form C-141
Hobbs District (GW-072)
BJ Services Company, USA
11211 FM 2920
Tomball, TX 77375

Dear Mr. Brown:

BJ Services Company, U.S.A. has enclosed New Mexico Oil Conservation District's Form C-141. This is being submitted as an initial report for a release that was discovered at the Hobbs District located at 2708 West County Road, Hobbs, NM.

If there are any questions or comments, please contact me at (281) 357-2573.

Thank You.

Josh Morrissette
HSE Specialist

Cc: Terry Smyers – BJ Services, Hobbs
File – BJ Services, Tomball

Enclosure