

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

NOV 05 2009

HOBBSCOCD

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

NOV 05 2009

HOBBSCOCD

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Southern Union Gas Services, Ltd.	Contact	Rose Slade
Address	P.O. Box 1226 Jal, N.M. 88252	Telephone No.	432-940-5147
Facility Name	Lea County Field Dept.	Facility Type	L-5 8" Natural Gas Gathering

Surface Owner: Millard Deck Estates	Mineral Owner:	Lease No.
-------------------------------------	----------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	21	21S	37E					Lea

Latitude N32 27.436 Longitude W103 09.935

NATURE OF RELEASE

Type of Release : Crude Oil, Produced water and Natural Gas	Volume of Release: 5bbls.	Volume Recovered	NONE
Source of Release : 8" Natural Gas Pipeline	Date and Hour of Occurrence not known	Date and Hour of Discovery	10/14/09 12:15 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Lecking		
By Whom? Rose Slade	Date and Hour: 10/14/09 at 2:50 p.m.		
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.		



If a Watercourse was Impacted, Describe Fully.*

WATER @ 5'

Describe Cause of Problem and Remedial Action Taken.*
The 8" Natural gas pipeline developed a leak operating at approximately 7-8 psi on the pipeline. The line was clamped and will be replaced at a later time.

Describe Area Affected and Cleanup Action Taken. Approximately 30x30 sq.ft. of pasture land was affected by the leak and temporary repair was done on the pipeline with replacement of pipeline to be done at a later date. Remediation started on 10/30/09 completed delineation on 11/3/09 and will sample per OCD guidelines. Final remediation will follow the NMOCD recommended guidelines for leaks and spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Rose L. Slade	Approved by  ENY. ENGINEER District Supervisor:	
Title: EHS Compliance Specialist	Approval Date: 10/26/09	Expiration Date: 12/28/09
E-mail Address: rose.slade@sug.com	Conditions of Approval: Delineate to CLEAN + 1. SUBMIT FINAL C-141	Attached <input type="checkbox"/>
Date: 10/21/09 Phone: 432-940-5147 (cell)	IRP: 09.11.2334	

* Attach Additional Sheets If Necessary

FGRL 0931037520