

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED
DEC 03 2009
HOBBSOCD

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address P.O. Box 1849, Eunice NM 88231	Telephone No. 575-390-4186
Facility Name EBDU Sat #5 (EBDU#60 nearest well)	Facility Type Production Facility

Surface Owner Lucille Bryant	Mineral Owner BLM	Lease No. 30-025-38113
------------------------------	-------------------	------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	14	21S	37E	1270	FNL	2310	FEL	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Hydrocarbon/Produced Water	Volume of Release 80	Volume Recovered 70
Source of Release Gasket on Firetube	11/29/09 730am	11/29/09 730am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson	
By Whom? Natalie Gladden	Date and Hour 11/30/09 715am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

WATER @ 28'

Describe Cause of Problem and Remedial Action Taken.*
Gasket on firetube broke releasing a mixture of hydrocarbon and produced water. Contamination spread out inside the containment walls, west of battery and sprayed a large area southwest of battery. 70bbls of total fluid was recovered.

Describe Area Affected and Cleanup Action Taken.*
Landowner requested that the pasture area be scrapped up and replaced with fresh topsoil. A local gang will excavate the contaminated soil from inside the containment walls, and remainder of location will be remediated to meet NMOCD guidelines to closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Natalie Gladden</i>	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	ENV ENGINEER: Approved by District Supervisor: <i>Jeffrey Salamy</i>	
Title: EH&S Environmental Tech	Approval Date: 12/09/09	Expiration Date: 02/09/10
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval: DELINEATE TO CLEANUP. SUBMIT FINAL C-141 BY 02/09/10.	Attached <input type="checkbox"/>
Date: 12/02/09 Phone: 575-390-4186		IRP-09-12-2363

* Attach Additional Sheets If Necessary

FGRL 09 34342770