

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

DEC 07 2009

HOBBSOCD

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Devon Energy	Contact <input type="checkbox"/> Roger Hernandez
Address P. O. Box 250 Artesia, NM 88211	Telephone No. <input type="checkbox"/> 575-748-5238
Facility Name Watkins 32 Battery	Facility Type <input type="checkbox"/> Oil Well

Surface Owner STATE	Mineral Owner	Lease No. <input type="checkbox"/>
---------------------	---------------	------------------------------------

LOCATION OF RELEASE NEARBY WELL WATRINS 329001
API # 30-625-31735-00-00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	15	18S	32E	1980	North	1650	West	Lea County

NATURE OF RELEASE

Type of Release Oil	Volume of Release 14 BO	Volume Recovered 9 BO
Source of Release Broken bottom site glass	Date and Hour of Occurrence 11-25-2009 10:45 AM	Date and Hour of Discovery 11-25-2009 10:45 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD - Lea County (did not get persons name)	
By Whom? <input type="checkbox"/> Ernie Duran	Date and Hour <input type="checkbox"/> 11-25-2009 2:30 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A
WATER @ 150'

Describe Cause of Problem and Remedial Action Taken.*
Bottom site glass on heater treater broke in half spilling 14 BO in dike, recovered 9 BO.

Describe Area Affected and Cleanup Action Taken.*
20'x20', called vacuum truck to pickup fluid, will rake, til, fertilize, all the spill was contained in the dike area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Ernie Duran</i>	OIL CONSERVATION DIVISION	
Printed Name: Ernie Duran for Roger Hernandez	Approved by <input type="checkbox"/> ENV. ENGINEER: District Supervisor: <i>Sherry Ray Perkins</i>	
Title: Assistant Production Foreman	Approval Date: 12/30/09	Expiration Date: 03/03/10
Date: November 30, 2009 Phone: 575-513-1768	Conditions of Approval: DELINEATED TO CLEAN +1. SUBMIT FINAL Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary. C-141 BY 03/03/10 (IRP-09-12-2372)

F GIRL 09-36531881