

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88203
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

RECEIVED
NOV 19 2009
HOBBSOCD

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Devon Energy	Contact <input type="checkbox"/> Roger Hernandez
Address P. O. Box 250 Artesia, NM 88211	Telephone No. <input type="checkbox"/> 575-748-5238
Facility Name Corbin West 19 Fed #1	Facility Type <input type="checkbox"/> Oil Well
Surface Owner <u>FEDERAL</u>	Mineral Owner
	Lease No. <input type="checkbox"/>

LOCATION OF RELEASE

API # 30.025.33468.00.00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	19	18S	33E	660	North	660	West	Lea County, NM

NATURE OF RELEASE

Type of Release Oil	Volume of Release 16 BO	Volume Recovered <input type="checkbox"/> 11 BO
Source of Release 500 bbl. Steel oil tank	Date and Hour of Occurrence November 11, 2009 2:00 PM	Date and Hour of Discovery <input type="checkbox"/> November 11, 2009 2:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM - Hobbs Office Trisha BadBear	
By Whom? <input type="checkbox"/> Ernie Duran	Date and Hour <input type="checkbox"/> November 12, 2009 8:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully *

N/A

WATER @ 60'

Describe Cause of Problem and Remedial Action Taken.*

1" hole developed approximately 3" from bottom of 500 bbl. Steel oil tank resulting in the spill. Vacuum truck was called immediately and oil was transferred to the other oil tank on location and it picked up the oil spilled on the ground. Oil was contained in the dyke area.

Describe Area Affected and Cleanup Action Taken.*

Area affected was approximately 30'x20', area will be raked, tilled, and fertilized.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

<i>Adrienne Verkler for Roger Hernandez</i>	Approved by <input checked="" type="checkbox"/> District Supervisor: <i>Heaffery Luking</i>	
Printed Name: Adrienne Verkler for Roger Hernandez	Approval Date: 12/31/09	Expiration Date: 03/04/10
Title: Roger Hernandez; Production Foreman	Conditions of Approval: DELINEATE TO	
Date: November 16, 2009 Phone: 575-748-5238	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

CLEAN UP SUBMIT FINAL C-141 BY 03/04/10

IRP-09-12-2374

F GIRL 0936541657