

District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED  
DEC 31 2009  
HOBBSUCD

RECEIVED  
DEC 31 2009  
HOBBSUCD

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company BOPCO, L.P.	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name Hat Mesa Federal 31 #2	Facility Type E&P

Surface Owner Federal	Mineral Owner Federal	Lease No.
-----------------------	-----------------------	-----------

**LOCATION OF RELEASE**

API# 30.025.34594.00.00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	31	24S 20S	33E					Lea

Latitude N 32.53494 Longitude W 103.696089

**NATURE OF RELEASE**

Type of Release: Crude oil, natural gas, and produced water	Volume of Release: 10 bbl crude oil and produced water	Volume Recovered: 5 bbls total volume
Source of Release: Stuffing Box Failure	Date and Hour of Occurrence 12/20/09, Hour unknown	Date and Hour of Discovery 12/20/09 8:30 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD on-call operator Robert Harrison	
By Whom? Tony Savoie	Date and Hour 12/20/09 9:41 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
WATER @ 70'

Describe Cause of Problem and Remedial Action Taken.\* The well head stuffing box rubbers failed due to high flowline pressure. The well was turned off by the individual who discovered the event.

Describe Area Affected and Cleanup Action Taken.\* An area measuring approximately 8500 sq.ft on the caliche well pad was affected by the release, the oil had puddled up in 3 locations, all of the free oil was vacuumed up. An area measuring approximately 20,000 sq.ft. of pasture land was affected with a light mist of crude oil, very little of the mist affected the soil. The vegetation in the pasture was mowed with a brush hog. The area will be remediated in accordance the the NMOCD and BLM guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	ENV ENGINEER: Approved by District Supervisor: <i>Stephany Laking</i>	
Title: Waste Mgmt. & Remediation Specialist	Approval Date: 01/08/10	Expiration Date: 03/08/10
E-mail Address: TASavoie@BassPet.com	Conditions of Approval: DELINEATE TO CLEAN UP, SUBMIT FINAL C-141 BY	Attached <input type="checkbox"/> IRP-10.1.2387
Date: 12/28/09	Phone: 432-556-8730	

\* Attach Additional Sheets If Necessary

FGRL1000848958

