

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

DEC 30 2009

HOBBSCOCD

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company BP America Production Company	Contact Lloyd May
Address PO Box 1089, Eunice, NM 88231	Telephone No. 575-394-1600
Facility Name Sunflower State 28-1	Facility Type Battery

Surface Owner State	Mineral Owner State	Lease No. API # 3002536695
----------------------------	----------------------------	-----------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	28	17S	34E	1460	South	660	East	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water, Oil	Volume of Release 14.9 bbl water; 0.1 bbl oil	Volume Recovered 14 bbl water; 0.1 bbl oil
Source of Release BS&W line on produced water tank	Date and Hour of Occurrence 12/27/09 9:00 am	Date and Hour of Discovery 12/27/09 13:45
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

3" Victaulic tee froze & split on BS&W line, BS&W valve on H2O tank had been left open which drained 14.9 bbls of fluid to lined containment. Picked up 14 bbls H2O and 0.1bbl oil with vacuum truck. Closed all tank BS&W valves to isolate BS&W line.

WATER @ 1301

Describe Area Affected, and Cleanup Action Taken.*

All fluid released was contained within the lined containment around the tank. Fluid was picked up by vacuum truck.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Lloyd May</i>	OIL CONSERVATION DIVISION	
Printed Name: Lloyd May	Approved by ENV ENGINEER: District Supervisor: <i>Jeffrey Salinger</i>	
Title: Operations Specialist & Team Leader Relief for SENM	Approval Date: <i>01/08/10</i>	Expiration Date:
E-mail Address: mayl4@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>12/29/2009</i> Phone: 575-394-1608		<i>IRP-10-1-2386</i>

* Attach Additional Sheets If Necessary

FGRL 1000836206