

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**  Initial Report  Final Report

Name of Company COG OPERATING LLC	Contact Kanicia Carrillo
Address 550 W. Texas, Suite 100 Midland, TX 79701	Telephone No. 432-685-4332
Facility Name - Pronghorn 529 Truck Site	Facility Type- Battery

Surface Owner Federal	Mineral Owner	Lease No. ROW#NM72767
-----------------------	---------------	-----------------------

**LOCATION OF RELEASE**

NEAREST WELL PEARSAZL BX 002  
API # 30.025.00822.00.00

Unit Letter J	Section 34	Township 17S	Range 32E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
---------------	------------	--------------	-----------	---------------	------------------	---------------	----------------	------------

Latitude N 32 37.332' Longitude W 103 45.193'

**NATURE OF RELEASE**

Type of Release- Produced water	Volume of Release-270 bbls	Volume Recovered- 250 bbls
Source of Release- Transfer pump	Date and Hour of Occurrence- 12/17/09	Date and Hour of Discovery 12/17/09
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson, Geoffrey Leking, Paul Evans	
By Whom? Rick Wright	Date and Hour 12/18/09 1:47pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
  
WATER @ 45'

Describe Cause of Problem and Remedial Action Taken.\*  
A Discharged hose failed on the transfer pump. The hose has been replaced with a high pressure hose.

Describe Area Affected and Cleanup Action Taken.\*  
All fluid was contained within the firewall which is lined with 40 mil plastic.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Kanicia Carrillo	Approved by <small>ENV ENGINEER / District Supervisor:</small>	
Title: Regulatory Analyst	Approval Date: 01/21/10	Expiration Date: 03/22/10
E-mail Address: kcarrillo@conchoresources.com	Conditions of Approval: GROSS CONTAMINATION SHOULD BE REMEDIATED, SUBMIT FINAL C-141 BY	
Date: 01/06/10 Phone: 432-685-4332	Attached <input type="checkbox"/> IRP-10.7.2400	

\* Attach Additional Sheets If Necessary

FGRL 1002159942