

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JAN 20 2010

HOBBSD

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report XX Final Report

Name of Company	Oxy USA WTP	Contact	Dusty Wilson
Address	1017 W. Stanolind Rd	Telephone No.	(575) 397-8247
Facility Name	J. F. Janda I # 11	Facility Type	Well and Storage

Surface Owner	BLM	Mineral Owner	Oxy, BLM	Lease No.	
---------------	-----	---------------	----------	-----------	--

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	2	23s	36e	560	N	2310	E	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil and Produce Water	Volume of Release	50 bo-55 bw	Volume Recovered	none
Source of Release	Tank struck by Lightning	Date and Hour of Occurrence	09/21/2009 11:00 pm	Date and Hour of Discovery	09/21/2009 1100 pm
Was Immediate Notice Given?	X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required				
By Whom?	CJ Summers	Date and Hour	09/21/2009	If YES, To Whom? NMOCD	
Was a Watercourse Reached?	<input type="checkbox"/> Yes X No				
If YES, Volume Impacting the Watercourse. n/a					

If a Watercourse was Impacted, Describe Fully.*



N/A

Describe Cause of Problem and Remedial Action Taken.*
Tank struck by lightning, exploded and released above stated liquids. Remediation efforts completed as follows. Soil samples and tests were gathered and analyzed from the site. The results were discussed with NMOCD personnel(Leking), and the following work plan was approved. A 6" excavation of the affected site with soils to be removed and placed at an approved disposal facility for storage. The excavated area was then to be backfilled with like clean soils. This site is closed.

Describe Area Affected and Cleanup Action Taken *

Remediated to NMOCD Requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Dusty L. Wilson	Approved by	ENV ENGINEER - District Supervisor: 
Title:	HES Specialist	Approval Date:	01/29/10 Expiration Date: —
E-mail Address:	dusty_wilson@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	01/10/2010 Phone: (575) 397-8210	IRP-09-10-2307	

• Attach Additional Sheets If Necessary