

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
JAN 20 2010
HOBBSCO

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Oxy USA WTP	Contact	Dusty Wilson
Address	1017 W. Stanolind Rd	Telephone No.	(575) 397-8247
Facility Name	MLMU North Injection Line	Facility Type	Produce Water Injection
Surface Owner	Kelly Meyers	Mineral Owner	Oxy, BLM
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	5	24s	37e					Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil and Produce Water	Volume of Release	5 bo-35 bw	Volume Recovered	none
Source of Release	Trunk Line Rupture	Date and Hour of Occurrence	08/19/2009	Date and Hour of Discovery	08/19/2009
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jeff Leking		
By Whom?	Dusty Wilson/via email	Date and Hour	8/24/2009		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	n/a		

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Trunk line ruptured due to corrosion. Remediation efforts completed. This site was closed as per discussion and agreements with NMOCD personnel.(Leking) The approved work plan consisted of the following. The affected area was excavated to a depth of 3', a 20 mil. Plastic liner was installed over the affected area, and the area backfilled with clean, like soils. The removed contaminates were hauled to an approved disposal facility. This site is closed.

Describe Area Affected and Cleanup Action Taken *
Remediated to NMOCD Requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Dusty L. Wilson	Approved by	
Title:	HES Specialist	Approval Date:	01/29/2010
E-mail Address:	dusty_wilson@oxy.com	Expiration Date:	—
Date:	01110/2010	Phone:	(575) 397-8210
		Conditions of Approval:	Attached <input type="checkbox"/>
		IRP-09-11-2316	

• Attach Additional Sheets If Necessary