

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**RECEIVED**

JAN 25 2010

**HOBBS**

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address P.O. Box 1849 Eunice, NM 88231	Telephone No. 575-390-4186
Facility Name WBDU #11	Facility Type Injection well

Surface Owner Deck Estate	Mineral Owner State of NM	Lease No. 30-025-20069
---------------------------	---------------------------	------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	4	21S	37E	660'	FSL	1980'	FEL	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 10bbbls	Volume Recovered 5bbbls
Source of Release Injection line	Date 1/22/10 515pm	Date 01/22/10 515pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Natalie Gladden	Date and Hour 01/25/10 835am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

WATER @ 24'

Describe Cause of Problem and Remedial Action Taken.\*

Injection line leak going to recently plugged well (WBDU #11). line was repaired. vacuum truck recovered standing fluid and saturated soil was scrapped from the surface until one-call could be cleared.

Describe Area Affected and Cleanup Action Taken.\*

Saturated soil will be excavated and hauled to Sundance Disposal. The plugging department will be reclaiming this location and will finalize the clean-up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Natalie Gladden</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Natalie Gladden	Approved by ENV ENGINEER District Supervisor: <i>Jeffrey Johnson</i>	
Title: EH&S Environmental Tech	Approval Date: 01/29/10	Expiration Date: 03/29/10
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval: SUBMIT FINAL C-141 BY 03/29/10	Attached <input type="checkbox"/>
Date: 1/25/10 Phone: 575-390-4186		IRP-10-1-2402

\* Attach Additional Sheets If Necessary

FCR 100315 8494