

District I
1625 N. French Dr., Hobbs, NM 88240

District II
1301 W Grand Avenue, Artesia, NM

District III
1000 Rio Brazos Road, Aztec, NM 87410

District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

RECEIVED

FEB 04 2010

HOBBSUCD

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company <u>ConocoPhillips Company</u>	Contact <u>Jesse A. Sosa</u>
Address <u>3300 N. "A" St., Bldg. 6 #247 Midland, TX 79705-5</u>	Telephone No. <u>(505)391-3126</u>
Facility Name <u>Britt B Battery</u>	Facility Type <u>Battery</u>
Surface Owner <u>NMOCB STATE</u>	Mineral Owner <u>BLM</u>
Lease No. <u>3002506104</u>	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	15	20S	37E	1980	South	1530	West	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release <u>Crude Oil</u>	Volume of Release <u>14</u>	Volume Recovered <u>10</u>
Source of Release <u>Leak on bottom of oil tank</u>	Date and Hour of Occurrence <u>1/29/10 0630</u>	Date and Hour of Discovery <u>1/29/10</u>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>NMOCB & BLM</u>	
By Whom? <u>Jesse Sosa</u>	Date and Hour <u>2/4/10 & 2/2/10</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

WATER @ 40'



Describe Cause of Problem and Remedial Action Taken.*

Upon arrival MSO noticed oil was seeping bottom an oil tank. Tank had developed a leak from bottom of tank. MSO shut in and isolated tanks and called hot oilers to transfer the oil into other oil tank. MSO called out a vaccum truck to pick up the spill. The vaccum truck picked up a total of 10 Bbls

Describe Area Affected and Cleanup Action Taken.*

Affected area was 30' x 50' of caliche pad. Notifications were made to supervision and regulatory agencies. Area was cleaned up bt Removing contaminated caliche and replaced with clean caliche.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCB rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCB marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCB acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: <u>Jesse A. Sosa</u>	Approved by <u>District Supervisor:</u> 	
Title: <u>HSER Lead</u>	Approval Date: <u>02/05/10</u>	Expiration Date: <u>04/05/10</u>
E-mail Address: <u>Jesse.A.Sosa@conocophillips.com</u>	Conditions of Approval: <u>DECLINATE TO CLEAN</u>	
Date: <u>02/04/10</u> Phone: <u>(505)391-3126</u>	*1. SUBMIT FINAL C-141 BY 04/05/10. Attached <input type="checkbox"/>	
		<u>IRP-10-2415</u>

* Attach Additional Sheets If Necessary

AGRL 1003632649