


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

30-015-33292 Release Notification and Corrective Action

NMLB/1004242112 OPERATOR Initial Report Final Report

Name of Company Devon Energy <i>6137</i>	Contact Shannon Moss, Foreman
Address 6488 Seven Rivers Hwy - P.O. Box 250	Telephone No. 575-748-5232
Facility Name Joell 6 #2	Facility Type

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter G	Section 6	Township 23S	Range 27E	Feet from the 1530	North/South Line FNL	Feet from the 1130	East/West Line FEL	County Eddy
-------------------------	---------------------	------------------------	---------------------	------------------------------	--------------------------------	------------------------------	------------------------------	-----------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 33 bbls	Volume Recovered 0
Source of Release Oil	Date and Hour of Occurrence 2 bbls	Date and Hour of Discovery 0
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD & BLM	
By Whom? Shannon Moss, Foreman	Date and Hour 01/16/2010 - 3:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Circulating valve on the back of the water tank had frozen and ruptured.		
Describe Area Affected and Cleanup Action Taken.* Operator made sure all valves dumping to this tank were shut and re-routed to another tank.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Mykol Horner</i>	OIL CONSERVATION DIVISION	
Printed Name: Mykol Horner	Approved by District Supervisor Signed By <i>Mike Benjamin</i>	
Title: Field Tech 1	Approval Date: FEB 11 2010	Expiration Date:
E-mail Address: mykol.horner@dvn.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: January 20, 2010 Phone: 575-748-0160	REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY: 3/11/10	

* Attach Additional Sheets If Necessary

NMLB/1004245510

2RP-386

New Mexico Energy, Minerals and Natural Resources Department

Bill Richardson

Governor

Jon Goldstein

Cabinet Secretary

Jim Noel

Deputy Cabinet Secretary

Mark Fesmire

Division Director

Oil Conservation Division



Devon Energy Corporation
PO Box 250
Artesia, NM 88211
ATTN: Shannon Moss

February 11, 2010

Reference: Joell 6 002 API: 30-015-33292 G-6-23s-27e Eddy County, New Mexico

Operator,

The New Mexico Oil Conservation Division District 2 Office (OCD) is in receipt of an initial report Form C-141 reporting a release of produced fluids at or near the above referenced well site. The release reportedly occurred on or about 1/6/2010. Please submit a corrective action work plan proposal (plan) for remediation, removal and/or clean up of contaminants that may be present at this site. The plan is to be formulated based on vertical and horizontal delineation of contamination, site ranking, and OCD rules, regulations and guidelines.

A publication is available to you on the OCD website to aid in formulation of this plan. The publication may be found as follows:

<http://www.emnrd.state.nm.us/ocd>

Click on each of the following items as they appear:

- Publications
- Environmental Handbook
- Miscellaneous Guidelines
- Remediation of Leaks, Spills and Releases

Please submit this plan to the OCD District 2 Office not later than 3/11/2010. Please include any remedial or clean up actions that may have been already performed.

Clean up/remediation requirements may be subject to other federal, state, local laws and/or regulations.

Sincerely,

Mike Bratcher

NMOCD District 2

1301 W. Grand Ave.

Artesia, NM 88210

575-748-1283 Ext.108

mike.bratcher@state.nm.us

2RP-386

