

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company <i>Sheridan</i>	Contact <i>KEITH HENSON</i>
Address <i>PO BOX 34, Suite 100, 9 Green Plaza Houston TX</i>	Telephone No. <i>432-260-9656</i>
Facility Name <i>North Vacuum Rbo North Unit</i>	Facility Type <i>MUD #</i>

Surface Owner <i>STATE</i>	Mineral Owner <i>STATE</i>	Lease No. XXXX
----------------------------	----------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter <i>M</i>	Section <i>14.01</i>	Township <i>17S</i>	Range <i>34E</i>	Feet from the	North/South Line	Feet from the	East/West Line	County <i>LEA</i>
----------------------	----------------------	---------------------	------------------	---------------	------------------	---------------	----------------	-------------------

Latitude *32.863896500* Longitude *103.51350250* NEARBY WELL NVANU"2" A"2"
32.51.50.01 *103.30.48.61* API# *30.025.31342.00.00*

NATURE OF RELEASE

Type of Release <i>HEADER</i>	Volume of Release <i>100 BBL</i>	Volume Recovered <i>75 BBL</i>
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery <i>11/24/09</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? <i>OCIO</i>	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <i>N/A</i>	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
"T" IN HEADER HAD WORN HOLE IN BOTTOM, VACUUM TRUCK WERE CALLED OUT TO RECOVER SPILL, OCCIDENT AND A PLAN OF ACTION WAS PLANNED.

Describe Area Affected and Cleanup Action Taken.*
AT AROUND PUMP JACK & HEADER WAS AFFECTED AREA AND DOWN A SMALL PART OF ROAD. AND PAIL TRUCKS WERE CALLED OUT TO CLEANUP SPILL, OCIO & WITH PLANNED A CLEANUP ACTION.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Keith Henson</i>	Approved by ENV. ENGINEER: <i>[Signature]</i>	
Printed Name: <i>Keith Henson</i>	District Supervisor: <i>[Signature]</i>	
Title: <i>Lease Operator</i>	Approval Date: <i>11/24/09</i>	Expiration Date: <i>01/25/10</i>
E-mail Address:	Conditions of Approval: <i>DELINATE TO CLEAN +1. SUBMIT FINAL C-141 BY</i>	Attached <input type="checkbox"/>
Date: <i>11.24.09</i> Phone: <i>432-260-9656</i>		<i>09.11.2358</i>

* Attach Additional Sheets If Necessary

FGRL 1004230546