

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company CHAPARRAL ENERGY LLC	Contact J.R. WILLINGHAM
Address 701 CEDAR LAKE BLVD, OKLA. CITY, OK 73114	Telephone No. (405)830-1217, (432) 561-9462
Facility Name YATES STATE # 1	Facility Type OIL & WATER STORAGE

Surface Owner TOMMY BURRUS	Mineral Owner	Lease No.(API) 30-025-30034
----------------------------	---------------	-----------------------------

**LOCATION OF RELEASE**

Unit Letter	Section 16	Township 12-5	Range 38-E	Feet from the	North/South Line	Feet from the	East/West Line	County LEA
-------------	------------	---------------	------------	---------------	------------------	---------------	----------------	------------

Latitude N-33 16.424 Longitude W 10305.786

**NATURE OF RELEASE**

Type of Release B S & W	Volume of Release 10 BBLS	Volume Recovered 0
Source of Release LEAK IN OIL TANK	Date and Hour of Occurrence UNKNOWN	Date and Hour of Discovery 3-24-08 3:PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? LARRY JOHNSON	
By Whom? TOMMY BURRUS	Date and Hour 3-24-08 - 3:PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**RECEIVED**

MAR 28 2008

**HOBBS OCD**

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
HOLE IN OLD OIL TANK  
DISCONNECT BAD TANK FROM BATTERY & REMOVE ALL LIQUIDS

Describe Area Affected and Cleanup Action Taken.\*  
10'X45' AROUND TANKS. ALL FLUIDS WERE CONTAINED INSIDE THE DYKES. REMOVE & PLACE CONTAMINATED SOIL ON PLASTIC. REPLACE WITH FRESH SOIL. HAUL CONTAMINATED SOIL TO REMEDIATION FACILITY

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>J.R. Willingham</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: J R WILLINGHAM	Approved by District Supervisor <i>L. Johnson</i> <b>ENVIRONMENTAL ENGINEER</b>	
Title: SR. PRODUCTION FOREMAN	Approval Date: 3-28-08	Expiration Date: 5-28-08
E-mail Address: jrww@chaparralenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/28/08 Phone: (405)830-1217	FULL DEMONSTRATION REQUIRED BEFORE ANY BACKFILL IS BEGUN. JRP # 1830	

\* Attach Additional Sheets If Necessary

FGRL1006039409

- Call & Discuss w/ J.R. 3-28-08 9:10am