


GW - 028

REPORTS

Facility-Wide GW Monitoring Reports (Maps)

2010 - Present



- LEGEND:
- MONITOR WELL LOCATION
 - RECOVERY WELL LOCATION
 - IRRIGATION WELL LOCATION
 - PIEZOMETER LOCATION
 - 0.24 FREE PHASE PRODUCT THICKNESS (FEET)



NAVAJO REFINING COMPANY
ARTESIA REFINERY, EDDY COUNTY, NEW MEXICO
2009 ANNUAL GROUNDWATER REPORT

**PHASE SEPARATED HYDROCARBON
THICKNESS ISOPLETHS (FEET)
SECOND SEMI-ANNUAL EVENT 2009**

ARCADIS

FIGURE
6

CITY/SYRACUSE DIV/GROUP-ENV-141 DBA Schilling LD:(Opt) PIC:(Opt) PM:(Recd) TM:(Opt) LVR:(Opt)ON="OFF"REF="G:\ENV\CADD\SYRACUSE\ACT\T\X\080836\0002\0001\DWG\080836C10.dwg LAYOUT: 6\$AVED: 2/26/2010 2:17 PM ACADVER: 17.05 (LMS TECH)PAGESETUP: ---PLOTSTYLETABLE: PLT\FULLCTB.PLOTTED: 2/26/2010 2:17 PM BY: SCHILLING, ADAM XREFS: 080836X01 IMAGES: PROJECTNAME: NAPL_figures_2.jpg 080836X00