

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report



Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100 Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Pronghorn 529 Truck Site	Facility Type	Battery
Surface Owner	Federal	Mineral Owner	
			Lease No. (ROW#) NM72767

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	34	17S	32E					LEA

Latitude N 32 37.332' Longitude W 103 45.193'

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	270 bbls	Volume Recovered	250 bbls
Source of Release	Transfer pump	Date and Hour of Occurrence	12/17/09	Date and Hour of Discovery	12/17/09
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
		Larry Johnson - OCD Geoffrey Leking - OCD Paul Evans - BLM			
By Whom?	Rick Wright	Date and Hour	12/18/09	1:47p.m.	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
WATER@45'					
Describe Cause of Problem and Remedial Action Taken.* A discharged hose failed on the transfer pump. The hose has been replaced with a high pressure hose.					
Describe Area Affected and Cleanup Action Taken.* All standing fluid was contained within the firewall which is lined with 20 mil plastic. Free fluid was picked up by vacuum truck and all impacted gravel was removed and replaced with clean gravel. Site is closed.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Josh Russo		ENY ENGINEER: Approved by District Supervisor: 			
Title: HSE Coordinator		Approval Date: 03/01/10		Expiration Date: —	
E-mail Address: jrusso@conchoresources.com		Conditions of Approval:		Attached <input type="checkbox"/>	
Date: 02/024/2010 Phone: 432-212-2399		IRP-10-1-2400			

* Attach Additional Sheets If Necessary