

RECEIVED

RECEIVED

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

MAK 03 2010
HOBBSUOD

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAK 03 2010
HOBBSUOD

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	CHESAPEAKE OPERATING, INC.	Contact	BRADLEY BLEVINS
Address	P. O. BOX 190 HOBBS, NM 88241	Telephone No.	505-391-1462
Facility Name	West Nadine SWD	Facility Type	Tank Battery

Surface Owner	PRIVATE	Mineral Owner		Lease No.	
---------------	---------	---------------	--	-----------	--

LOCATION OF RELEASE

NEARBY WELL FRED TURNER 002
30.025.07739 00.00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	6	20S	38E					LEA

Latitude N 32.59673 Longitude W 103.18565

NATURE OF RELEASE

Type of Release	Produced water and oil	Volume of Release	50 bbls	Volume Recovered	5 bbls
Source of Release	Pump seals failure	Date and Hour of Occurrence	3-2-2010 8:00 a.m.	Date and Hour of Discovery	3-2-2010 10:00 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Bradley Blevins	Geoff Leking			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Date and Hour 3/3/10 9:19 a.m.			
If YES, Volume Impacting the Watercourse.					

If a Watercourse was Impacted, Describe Fully.*

WATER @ 60'

Describe Cause of Problem and Remedial Action Taken.*

The seals on a transfer pump failed releasing a combination of oil and produced water to ground surface. Approximately 50 barrels of fluid was released. A vacuum truck was used to pick up free fluid.

Describe Area Affected and Cleanup Action Taken.*

Impacted soil removal was commenced on 3-2-10. Impacted soil will be removed and samples taken. The sample results will be discussed with the NMOCD to formalize a remediation plan. Upon completion, a final C-141 will be submitted.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: *Bradley Blevins*

Printed Name: Bradley Blevins

Title: HSE Specialist

E-mail Address: Bradley.blevins@chk.com

Date: 3/3/10 Phone: 575-391-1462

ENV ENGINEER :

Approved by District Supervisor: *Geoff Leking*

Approval Date: 03/08/10 Expiration Date: 05/10/10

Conditions of Approval: DELINEATE TO CLEAN + 1. SUBMIT FINAL C-141 BY
Attached
IRP-10-3-2445

* Attach Additional Sheets If Necessary

FGRL100 6726587

Leking, Geoffrey R, EMNRD

From: Cliff P. Brunson [cbrunson@bbcinternational.com]
Sent: Wednesday, March 03, 2010 4:00 PM
To: 'Bradley Blevins'; Leking, Geoffrey R, EMNRD
Cc: 'Ken Swinney'; 'Jennifer'
Subject: RE: West Nadine SWD- Release

Geoff,

Please correct the range to 38E not 37E. The initial C-141 will be correct when you receive it.

Thanks, Cliff

From: Bradley Blevins [mailto:bradley.blevins@chk.com]
Sent: Wednesday, March 03, 2010 9:19 AM
To: Leking, Geoffrey R, EMNRD
Cc: Cliff P. Brunson; Ken Swinney; Jennifer
Subject: West Nadine SWD- Release

Geoff,

Chesapeake had a release on the West Nadine SWD, the seals on the pump broke releasing a combination of oil and water to the ground surface. Cliff Brunson with BBC will follow up with C-141. If you have any questions or need further information please give me a call.

UNIT 0
SEC 6
T20S
R37E
50 BARRELS OIL WATER COMBO
5 BARRELS RECOVERED
DISCOVERED 3-2-2010 @ 10:00AM

Bradley Blevins
EH & S Field Specialist
Hobbs Field Office
North Permian Division
Office: (575) 391-1462 x 86424
Cell: (575) 441-0341
Fax: (575)391-6679



This email (and attachments if any) is intended only for the use of the individual or entity to which it is addressed, and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this email is not the intended recipient, or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately by return email and destroy all copies of the email (and attachments if any).
