

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Chevron Mid-Continent LP	Contact	Kim Klahsen
Address	HCR 60 Box 423 Lovington, NM 88260	Telephone No.	575-396-4414 X 128 432-894-3298 (Cell)
Facility Name	West Lovington Well # 41	Facility Type	Injection Well

Surface Owner	Chevron	Mineral Owner	State of NM	Lease No.	B-4120-1
---------------	---------	---------------	-------------	-----------	----------

LOCATION OF RELEASE

API# 30 025 03901 00 00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	07	17 S	36 E	660	FNL	1980	FEL	Lea

Latitude N 32 degree 51 minutes 17.2 seconds Longitude W 103 degrees 23 minutes 31 seconds

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	20 bbl	Volume Recovered	14 bbl
Source of Release	injection line	Date and Hour of Occurrence	3/27/09	Date and Hour of Discovery	3/27/09 7:30 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Larry Ridenour	Date and Hour 3/27/09 10:41 AM			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*
No Impact to watercourse.

Describe Cause of Problem and Remedial Action Taken.*

An injection line leaked below ground. Water pooled on the surface and a vacuum truck was immediately dispatched to recover the pooled water. A work order was completed to remove several inches of contaminated soil.

Describe Area Affected and Cleanup Action Taken.*

The Vacuum truck recovered 14 bbls of produced water. Surface soil will be removed with a backhoe. A plan will be developed and submitted for approval.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:	Approved by <u>ENV ENGINEER</u> District Supervisor: <u>[Signature]</u>	
Printed Name: Kim Klahsen	Approval Date: 03/08/10	Expiration Date: 05/10/10
Title: HES Specialist	Conditions of Approval: DELIVERATE TO CLEAN	
E-mail Address: KDKL@chevron.com	+1. SUBMIT FINAL C-141 BY _____ Attached <input type="checkbox"/>	
Date: 4/2/09	Phone: 575-396-4414	IRP-10-3-2446

FGRL1006730948