

Bratcher, Mike, EMNRD

From: Curtis Elam [ce_elkeenv@yahoo.com]
Sent: Tuesday, April 06, 2010 3:30 PM
To: Bratcher, Mike, EMNRD
Subject: Aminded remediation CA russel batter, Linn Operating
Attachments: Aminded remediation.doc

Here is the aminded remediation plan for the ca russel.

Curtis elam

ce_elkeenv@yahoo.com

432-296-8472

Elke Environmental, Inc.

P.O. Box 14167 Odessa, TX 79768
Phone (432) 366-0043 Fax (432) 366-0884

April 6, 2010

New Mexico Oil Conservation Division
Mr. Mike Bratcher
1301 West Grand Ave.
Artesia, New Mexico 88210

Re: Linn Operating – C A Russell Battery
UL 'B' Sec. 18 T17S R31E Eddy County
2RP-392

Mr. Mike Bratcher,

E.L.K.E Environmental proposes to excavate test points one, two three and four to a dept of two foot and test point five to a depth of three foot. The excavated soil will be hauled off and replaced with clean native soil or caliche. E.L.K.E will sample the bottom of the excavation at the time the proposed depth is reached. Lab analysis will be preformed to prove B-Tex is below RAL's . The excavation will continue until the bottom samples reflect results satisfactory to the OCD.

Curtis Elam.