

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**  
APR 08 2010  
HOBBSCOCD

Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Ranger 40	Contact	Alan Standafer
Address	1009 Collier way Suite # 206	Telephone No.	432-557-8722
Facility Name	<del>Injection well</del> # 98 LDU	Facility Type	Production Well
Surface Owner	Randy Crawford	Mineral Owner	
		Lease No.	# 98

**LOCATION OF RELEASE** API# 30-025-27843-00-00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	32	24	37	N/A	N/A	N/A	N/A	Lea

Latitude N 32° 10.376 Longitude W 108° 10.862

**NATURE OF RELEASE**

Type of Release	Produced water / skin Oil	Volume of Release	140 BBL	Volume Recovered	120
Source of Release	Injection Line	Date and Hour of Occurrence	3-27	Date and Hour of Discovery	3-27-10
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	8:00 a.m.		10:00 a.m.
By Whom?	Phillip Little SUGS	Date and Hour	3-27-10		10:30 a.m.
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

none

Describe Cause of Problem and Remedial Action Taken.\*

Steel line had hole dug out area and fixed leak going to scrape top and haul off to disposal then get with OCP to come up with remediation plan

Describe Area Affected and Cleanup Action Taken.\*

Pasture south of satellite #4 was impacted plan to fix leak scrape surface and haul off then get with OCP for remediation plan

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Alan Standafer</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Alan Standafer	ENV. ENGINEER:	Approved by District Supervisor: <i>Geoffrey Lakin</i>
Title:	Contract Pump #6	Approval Date:	04/08/10
E-mail Address:		Expiration Date:	06/08/10
Date:	Phone: (434) 557-8722	Conditions of Approval:	DELIVER TO CLEAN + 1 - SUBMIT
		Attached	<input type="checkbox"/>
		IRP-10.4.2472	

\* Attach Additional Sheets If Necessary