

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Targa Midstream Services L P	Contact: James Lingnau 575.394.2534, Chuck Tolsma 575.631.6026
Address: PO Box 1909 Eunice, NM 88231	Telephone No. (575) 394-2534
Facility Name: Eunice Gas Plant <i>EUNICE GAS PLANT SMD #1</i>	Facility Type: Natural Gas Gathering System

Surface Owner: J. D. Martin	Mineral Owner:	Lease No. <i>API # 30.025.21A97</i>
-----------------------------	----------------	-------------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>D</i>	22	22S	37E					Lea

Latitude 32.37779N Longitude 103.15011

NATURE OF RELEASE

Type of Release: Natural Gas and liquid from a 8 inch gathering line with 12 psi flowing 100MCFD.	Volume of Release: Approximately 5 Barrels of liquid and 40mcf of natural gas by calculation	Volume Recovered: NONE
Source of Release: Natural gas 8 inch gathering line with 1/4 inch holes from external corrosion.	Date and Hour of Occurrence: 7 AM March 23, 2010	Date and Hour of Discovery 10 AM March 23, 2010
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson OCD in Hobbs by phone and to OCD on call phone	
By Whom? Roger Holland	Date and Hour 11AM March 23, 2010	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken. *

8 inch natural gas gathering line developed 1/4 inch holes from corrosion. Line was shut in and 200 feet of 6 inch poly line was inserted. Contaminated soil will be excavated and disposed of in an OCD approved landfarm.

Describe Area Affected and Cleanup Action Taken.*

The area affected will be excavated and soil contamination disposed of. Area will be cleaned and sampled to insure compliance with OCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Don Embrey</i>	OIL CONSERVATION DIVISION <i>L. Johnson</i>	
Printed Name: Don Embrey	Approved by District ENVIRONMENTAL ENGINEER	
Title: Training Specialist	Approval Date: <i>3.30.10</i>	Expiration Date: <i>5.30.10</i>
E-mail Address: dembrey@targaresources.com	Conditions of Approval: <i>SUBMIT FINAL C-141 w/DOCS B4</i> Attached <input type="checkbox"/>	
Date: March 23, 2010 Phone: (432) 688-0546	<i>IRP# 10.3.2465</i>	

* Attach Additional Sheets If Necessary