


District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

30-015-35296

Release Notification and Corrective Action

nMLB1010538127

OPERATOR

X Initial Report Final Report

Name of Company	Oxy USA WTP	16696	Contact	Dusty Wilson
Address	1017 W. Stanolind Rd		Telephone No.	(575) 397-8247
Facility Name	Pure Gold A # 8 Battery		Facility Type	Storage

Surface Owner	State of NM	Mineral Owner	Shared	Lease No.	NM-3846
---------------	-------------	---------------	--------	-----------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	21	23s	31e					Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produce Water	Volume of Release	200 bbls	Volume Recovered	150 bbls
Source of Release	Poly Flow line ruptured due to improper installation	Date and Hour of Occurrence	12/16/09	Date and Hour of Discovery	Same
Was Immediate Notice Given?	X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher		
By Whom?	Dusty Wilson	Date and Hour	12/28/09 0800 hrs		
Was a Watercourse Reached?	<input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	n/a		

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken *

Flow line ruptured due to 3' poly line was scarred during installation. All free standing fluids were recovered via Vac Truck upon discovery. Remediation efforts will be ongoing. Line was repaired.

Describe Area Affected and Cleanup Action Taken.*

Remediate to NMOCD Requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Dusty L. Wilson	Approved by:	Supervisor: _____
Title: HES Specialist	Approval Date: APR 15 2010	Expiration Date: JUN 15 2010
E-mail Address: dusty_wilson@oxy.com	Conditions of Approval: REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY: MAY 15 2010	Attached <input type="checkbox"/>
Date: 12/29/2009 Phone: (575) 397-8210		

- Attach Additional Sheets If Necessary

nMLB1010539254 Release site - UTM
32.28621 x 103.78764

2RP-405