

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: Southern Union Gas Services	Contact: Rose Slade
Address: P.O. Box 1226 Jal, N.M. 88252	Telephone No.: 432-940-5147
Facility Name: Lea County Field Dept.	Facility Type: Hawk Compressor Station

Surface Owner : State of New Mexico land	Mineral Owner	Lease No.
------------------------------------------	---------------	-----------

**LOCATION OF RELEASE**

API # 30-025-38822-00-00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	16	21 South	37 East					

Latitude 32°28.772 North Longitude 103°10.019

**NATURE OF RELEASE**

Type of Release: Natural Gas	Volume of Release: 137 MCF	Volume Recovered: N/A
Source of Release: Blowing down pipeline	Date and Hour of Occurrence: 2/12/2010 @ 9:52 am	Date and Hour of Discovery: N/A
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking (OCD)	
By Whom? Rose Slade	Date and Hour: 2/12/2010 @ 1:56 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

N/A

WATER @ 63'



Describe Cause of Problem and Remedial Action Taken.\*

Blew down the 8" hawk line the starting pressure was 950 psi at 9:52 am and the pressure when stopped was at 665 psi. The length of the pipeline that was blown down is approximately 4.4 miles and the discharge meter # is 02282. The total MCF that was blown down was 137 MCF.

Describe Area Affected and Cleanup Action Taken.\*

N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Rosa L. Slade	Approved by <u>ENV. ENGINEER</u> District Supervisor: 	
Title: EHS Compliance Specialist	Approval Date: 04/05/10	Expiration Date: -
E-mail Address: rose.slade@sug.com	Conditions of Approval:	
Date: 2/15/2010 Phone: 432-940-5147	Attached <input type="checkbox"/> RP-10-4-2468	

\* Attach Additional Sheets If Necessary

FIGURE 1009528